

ABON

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--------------------------|
| T12018 | 40.685 | Fixed Code | Not compatible with HL5. |
| T12030 | 40.685 | Fixed Code | Not compatible with HL5. |
| 1K AM HS | 433.92 | Rolling Code | |
| 4K AM HS | 433.92 | Rolling Code | |

Achenbach

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| RFKCO-40-5 | 40.685 | Fixed Code | Not compatible with HL5. |
| T102497-40-5 | 40.685 | Fixed Code | Not compatible with HL5. |
| T397-40-2 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX02-40-2 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX03-40-1/5 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX04-40-15 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX03-868-4 | 868.35 | Rolling Code | compatible since HomeLink Software Version 7 |

AET

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|------------|--------------------------|
| TX 40 | 40.685 | Fixed Code | Not compatible with HL5. |

AKM

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| T102497-40-5 | 40.685 | Fixed Code | Not compatible with HL5. |
| T397-40-2 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX03-868-4 | 868.35 | Rolling Code | compatible since HomeLink Software Version 7 |

Allmatic

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|------------|--------------------------|
| AKMY 1 | 30.875 | Fixed Code | Not compatible with HL5. |
| AKMY 2 | 30.875 | Fixed Code | Not compatible with HL5. |
| AKMY 4 | 30.875 | Fixed Code | Not compatible with HL5. |
| AKMY 1 | 40.665 | Fixed Code | Not compatible with HL5. |
| AKMY 2 | 40.665 | Fixed Code | Not compatible with HL5. |
| AKMY 4 | 40.665 | Fixed Code | Not compatible with HL5. |
| AEMX1 | 433.92 | Fixed Code | |

| | | | |
|-----------|--------|--------------|--|
| AEMX2 | 433.92 | Fixed Code | |
| AEMX4 | 433.92 | Fixed Code | |
| B.RO STAR | 433.92 | Rolling Code | |
| B.RO1WN | 433.92 | Rolling Code | |
| B.RO2WN | 433.92 | Rolling Code | |
| B.RO4WN | 433.92 | Rolling Code | |
| B.ROT12W | 433.92 | Rolling Code | |
| B.ROVER | 433.92 | Rolling Code | |

Alltronik

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|------------|--------------------------|
| S206 | 27.015 | Fixed Code | Not compatible with HL5. |
| S215 | 27.015 | Fixed Code | Not compatible with HL5. |
| S235 | 27.015 | Fixed Code | Not compatible with HL5. |
| S 415 | 27.02 | Fixed Code | Not compatible with HL5. |
| S406 | 40.685 | Fixed Code | Not compatible with HL5. |
| S435-10 | 40.685 | Fixed Code | Not compatible with HL5. |
| S435-40 | 40.685 | Fixed Code | Not compatible with HL5. |
| S435B | 40.685 | Fixed Code | Not compatible with HL5. |
| S 415 | 40.69 | Fixed Code | Not compatible with HL5. |
| S 406 | 433.91 | Fixed Code | |

ALUFORJA

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

ALUKON

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|------------|--|
| Comfort 220 | 868.3 | Fixed Code | compatible since HomeLink Software Version 7 |
| MT87A1-1 | 868.5 | Fixed Code | compatible since HomeLink Software Version 7 |
| MT87A1-2 | 868.5 | Fixed Code | compatible since HomeLink Software Version 7 |
| MT87A1-4 | 868.5 | Fixed Code | compatible since HomeLink Software Version 7 |

ALULUX

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|------------|--|
| HS40A8 | 40.685 | Fixed Code | Not compatible with HL5. |
| MT40A1 1-Kanal | 40.685 | Fixed Code | Not compatible with HL5. |
| MT40A1 2-Kanal | 40.685 | Fixed Code | Not compatible with HL5. |
| Digital 302 | 433.92 | Fixed Code | |
| Digital 302 | 868.3 | Fixed Code | compatible since HomeLink Software Version 7 |
| Digital 304 | 868.3 | Fixed Code | compatible since HomeLink Software Version 7 |
| MT87A1 1-Kanal | 868.5 | Fixed Code | compatible since HomeLink Software Version 7 |
| MT87A1 2-Kanal | 868.5 | Fixed Code | compatible since HomeLink Software Version 7 |
| MT87A1 4-Kanal | 868.5 | Fixed Code | compatible since HomeLink Software Version 7 |

Alutec

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|------------|--------------------------|
| RFKCO-40-5 | 40.685 | Fixed Code | Not compatible with HL5. |
| T102497-40-5 | 40.685 | Fixed Code | Not compatible with HL5. |
| T397-40-2 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX02-40-2 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX03-40-1/5 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX04-40-15 | 40.685 | Fixed Code | Not compatible with HL5. |

Amboss

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| TX03-868-4 | 868.35 | Rolling Code | compatible since HomeLink Software Version 7 |

Amsiko

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| TX03-868-4 | 868.35 | Rolling Code | compatible since HomeLink Software Version 7 |

Angelmir

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| TX03-868-4 | 868.35 | Rolling Code | compatible since HomeLink Software Version 7 |

Ansonic

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| SF40... | 40.662 | Fixed Code | Not compatible with HL5. |
| SA40... | 40.685 | Fixed Code | Not compatible with HL5. |
| SF433... | 433.075 | Fixed Code | compatible since HomeLink Software Version 7 |
| SA434... | 433.92 | Fixed Code | |
| SA868... | 868.35 | Rolling Code | compatible since HomeLink Software Version 7 |

Antech Antriebstechnik

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|-----------------------------------|------------------|--------------|--|
| (BT40) 131500-10 | 40.685 | Fixed Code | Not compatible with HL5. |
| (BT40) 131500-20 | 40.685 | Fixed Code | Not compatible with HL5. |
| (BT40) 131500-30 | 40.685 | Fixed Code | Not compatible with HL5. |
| 4 Kanal 433,92 MHz 60030020 | 433.92 | Rolling Code | |
| 4 Kanal Multifrequenz 60030010 | 433.92 and 868.3 | Rolling Code | compatible since HomeLink Software Version 7 |

Aperto

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| T102497-27-5 | 27.045 | Fixed Code | Not compatible with HL5. |
| RFKCO-40-5 | 40.685 | Fixed Code | Not compatible with HL5. |
| T102497-40-5 | 40.685 | Fixed Code | Not compatible with HL5. |
| T397-40-2 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX02-40-2 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX03-40-1/5 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX04-40-15 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX03-434-2 | 434.42 | Rolling Code | |
| TX03-434-4 | 434.42 | Rolling Code | |
| TX03-434-4-XP | 434.42 | Rolling Code | |
| TX03-8-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |
| TX03-868-4-XP | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

Aprimatic

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|------------|--------------------------|
| TG2M | 27.195 | Fixed Code | Not compatible with HL5. |
| TG4M | 27.195 | Fixed Code | Not compatible with HL5. |
| - | 30.895 | Fixed Code | Not compatible with HL5. |

Araujo

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

ATEC

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| RFKCO-40-5 | 40.685 | Fixed Code | Not compatible with HL5. |
| T102497-40-5 | 40.685 | Fixed Code | Not compatible with HL5. |
| T397-40-2 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX02-40-2 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX03-40-1/5 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX04-40-15 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

Atodor

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|------------|--------------------------|
| G 750 EML | 27.145 | Fixed Code | Not compatible with HL5. |
| G4330E | 433.92 | Fixed Code | |
| G4332E | 433.92 | Fixed Code | |
| G4333E | 433.92 | Fixed Code | |
| G4335E | 433.92 | Fixed Code | |

Attas / Dickert

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|------------|--------------------------|
| HS DX27 | 27.015 | Fixed Code | Not compatible with HL5. |

Aufinger

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|------------|--------------------------|
| 2710N | 27.015 | Fixed Code | Not compatible with HL5. |
| 4010N | 40.685 | Fixed Code | Not compatible with HL5. |

Compatible Device Manufacturers

If your device is not listed here, it may not be compatible with HomeLink. Don't see your device? [Get a universal receiver here.](#)

| | | | |
|------|--------|------------|--|
| 433N | 433.92 | Fixed Code | compatible since HomeLink Software Version 7 |
| 434N | 433.92 | Fixed Code | |

Autodoor

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|------------|--------------------------|
| 1A4443-2 | 27.045 | Fixed Code | Not compatible with HL5. |

AZIRA

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

B&D

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|------------|-------|
| 62170 | 433.92 | Fixed Code | |

BAME

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|-------|
| BAME-MIZAR | 433.92 | Fixed Code | |
| Joy | 433.92 | Rolling Code | |
| JOY | 433.92 | Rolling Code | |
| King 2 | 433.92 | Fixed Code | |
| Mizar | 433.92 | Fixed Code | |

Bartelt

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

BBG

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

Becker

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|------------|--------------------------|
| 1K | 27.015 | Fixed Code | Not compatible with HL5. |
| 2K | 27.015 | Fixed Code | Not compatible with HL5. |
| 3K | 27.015 | Fixed Code | Not compatible with HL5. |
| 1K | 40.685 | Fixed Code | Not compatible with HL5. |
| 1K Mini or Maxi | 40.685 | Fixed Code | Not compatible with HL5. |
| 2K | 40.685 | Fixed Code | Not compatible with HL5. |
| 3K | 40.685 | Fixed Code | Not compatible with HL5. |
| 4K | 40.685 | Fixed Code | Not compatible with HL5. |
| 4K Mini or Maxi | 40.685 | Fixed Code | Not compatible with HL5. |

BelFox

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------|-------|
|------------------|-----------------|--------|-------|

Compatible Device Manufacturers

If your device is not listed here, it may not be compatible with HomeLink. Don't see your device? [Get a universal receiver here.](#)

| | | | |
|---------------|--------|------------|--|
| 7120 | 27.015 | Fixed Code | Not compatible with HL5. |
| 7121 | 27.015 | Fixed Code | Not compatible with HL5. |
| 7122 | 27.015 | Fixed Code | Not compatible with HL5. |
| 7123 | 27.015 | Fixed Code | Not compatible with HL5. |
| 7130 | 27.015 | Fixed Code | Not compatible with HL5. |
| 7131 | 27.015 | Fixed Code | Not compatible with HL5. |
| 7132 | 27.015 | Fixed Code | Not compatible with HL5. |
| 7133 | 27.015 | Fixed Code | Not compatible with HL5. |
| 7330 | 27.015 | Fixed Code | Not compatible with HL5. |
| 7331 | 27.015 | Fixed Code | Not compatible with HL5. |
| 7350 | 27.015 | Fixed Code | Not compatible with HL5. |
| 7120 | 40.685 | Fixed Code | Not compatible with HL5. |
| 7121 | 40.685 | Fixed Code | Not compatible with HL5. |
| 7122 | 40.685 | Fixed Code | Not compatible with HL5. |
| 7123 | 40.685 | Fixed Code | Not compatible with HL5. |
| 7230 | 40.685 | Fixed Code | Not compatible with HL5. |
| 7231 | 40.685 | Fixed Code | Not compatible with HL5. |
| 7232 | 40.685 | Fixed Code | Not compatible with HL5. |
| 7233 | 40.685 | Fixed Code | Not compatible with HL5. |
| 7430 | 40.685 | Fixed Code | Not compatible with HL5. |
| 7431 | 40.685 | Fixed Code | Not compatible with HL5. |
| 7450 | 40.685 | Fixed Code | Not compatible with HL5. |
| 7730 | 433.92 | Fixed Code | |
| 7731 | 433.92 | Fixed Code | |
| 7732 | 433.92 | Fixed Code | |
| 7733 | 433.92 | Fixed Code | |
| 7834 | 868.3 | Fixed Code | compatible since HomeLink Software Version 7 |
| 7834-E | 868.3 | Fixed Code | compatible since HomeLink SW version 7 |
| 7834-E-2 | 868.3 | Fixed Code | compatible since HomeLink SW version 7 |
| 7834-E-4 | 868.3 | Fixed Code | compatible since HomeLink SW version 7 |
| 7834-E-M(att) | 868.3 | Fixed Code | compatible since HomeLink SW version 7 |
| 7834-mini | 868.3 | Fixed Code | compatible since HomeLink Software Version 7 |

BeluTec

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|------------|--------------------------|
| RFKCO-40-5 | 40.685 | Fixed Code | Not compatible with HL5. |
| T102497-40-5 | 40.685 | Fixed Code | Not compatible with HL5. |

Compatible Device Manufacturers

If your device is not listed here, it may not be compatible with HomeLink. Don't see your device? [Get a universal receiver here.](#)

| | | | |
|-------------|--------|--------------|--|
| T397-40-2 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX02-40-2 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX03-40-1/5 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX04-40-15 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

Beninca

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| LOT1E | 30.875 | Fixed Code | Not compatible with HL5. |
| LOT2E | 30.875 | Fixed Code | Not compatible with HL5. |
| LOT4E | 30.875 | Fixed Code | Not compatible with HL5. |
| LO.T2W | 433.92 | Fixed Code | |
| LO.T2WMR | 433.92 | Fixed Code | |
| LO.T2WMS | 433.92 | Fixed Code | |
| LO.T4W | 433.92 | Fixed Code | |
| ROLLKEY DELUXE | 433.92 | Rolling Code | compatible since HomeLink Software Version 7 |
| ROLLKEY ELEGANT | 433.92 | Rolling Code | compatible since HomeLink Software Version 7 |
| T2WK | 433.92 | Fixed Code | |
| T2WV | 433.92 | Rolling Code | compatible since HomeLink Software Version 7 |
| T4WK | 433.92 | Fixed Code | |
| T4WV | 433.92 | Rolling Code | compatible since HomeLink Software Version 7 |

Berlemann

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|------------|--|
| INOVA 27 4k | 27.015 | Fixed Code | Not compatible with HL5.compatible since HomeLink Software Version 7 |
| INOVA 40 4k | 40.685 | Fixed Code | Not compatible with HL5.compatible since HomeLink Software Version 7 |
| INOVA 433 2K | 433.92 | Fixed Code | compatible since HomeLink Software Version 7 |
| INOVA 433 4k | 433.92 | Fixed Code | compatible since HomeLink Software Version 7 |
| INOVA 434 1k | 433.92 | Fixed Code | compatible since HomeLink Software Version 7 |

| | | | |
|--------------|--------|------------|--|
| INOVA 434 4k | 433.92 | Fixed Code | compatible since HomeLink Software Version 7 |
|--------------|--------|------------|--|

Bernal

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|-------------------|-----------------|--------------|--|
| SM-1 | 26.995 | Fixed Code | Not compatible with HL5. |
| B1S27L | 27 | Fixed Code | Not compatible with HL5. |
| 02 0001 00 | 27.015 | Fixed Code | Not compatible with HL5. |
| BE27L | 27.015 | Fixed Code | Not compatible with HL5. |
| - | 27.12 | Fixed Code | Not compatible with HL5. |
| B1S40L | 40.685 | Fixed Code | Not compatible with HL5. |
| BE40L | 40.685 | Fixed Code | Not compatible with HL5. |
| B.RO1WN | 433.92 | Rolling Code | |
| B.RO2WN | 433.92 | Rolling Code | |
| B.RO4WN | 433.92 | Rolling Code | |
| RC1 | 433.92 | Rolling Code | |
| MT87A2B / 2 Kanal | 868.3 | Rolling Code | compatible since HomeLink Software Version 7 |
| MT87A2B / 4 Kanal | 868.3 | Rolling Code | compatible since HomeLink Software Version 7 |

Berner Torantriebe

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--------------------------|
| SM1/SM1MD | 26.995 | Fixed Code | Not compatible with HL5. |
| SM2/SM2MD | 26.995 | Fixed Code | Not compatible with HL5. |
| SM4/SM4MD | 26.995 | Fixed Code | Not compatible with HL5. |
| B1S27L | 27.015 | Fixed Code | Not compatible with HL5. |
| B2S27L | 27.015 | Fixed Code | Not compatible with HL5. |
| B3S27L | 27.015 | Fixed Code | Not compatible with HL5. |
| B4S27L | 27.015 | Fixed Code | Not compatible with HL5. |
| BE 27 L | 27.015 | Fixed Code | Not compatible with HL5. |
| B140L | 40.685 | Fixed Code | Not compatible with HL5. |
| B1S40L | 40.685 | Fixed Code | Not compatible with HL5. |
| B240L | 40.685 | Fixed Code | Not compatible with HL5. |
| B2S40L | 40.685 | Fixed Code | Not compatible with HL5. |
| B3S40L | 40.685 | Fixed Code | Not compatible with HL5. |
| B440L | 40.685 | Fixed Code | Not compatible with HL5. |
| B4S40L | 40.685 | Fixed Code | Not compatible with HL5. |
| BE 40 L | 40.685 | Fixed Code | Not compatible with HL5. |
| RC1 | 433.92 | Rolling Code | |
| RC2 | 433.92 | Rolling Code | |
| RC4 | 433.92 | Rolling Code | |

Compatible Device Manufacturers

If your device is not listed here, it may not be compatible with HomeLink. Don't see your device? [Get a universal receiver here.](#)

| | | | |
|-----------|--------|--------------|--|
| SKX1MD | 433.92 | Fixed Code | |
| SKX2MD | 433.92 | Fixed Code | |
| SKX3MD | 433.92 | Fixed Code | |
| SKX4MD | 433.92 | Fixed Code | |
| BHS140 LS | 868.30 | Fixed Code | compatible since Software version 7 |
| RCBE868/4 | 868.36 | Rolling Code | compatible since HomeLink Software Version 7 |

BFT

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|------------|-------|
| TEO-1 | 433.92 | Fixed Code | |
| TEO-2 | 433.92 | Fixed Code | |
| TEO-4 | 433.92 | Fixed Code | |

Big Tor

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

Bistag

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

BKF

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

Blasl

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

Bosch

| | | | |
|--|--|--|--|
| | | | |
|--|--|--|--|

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|------------|--------------------------|
| 7 781 999 720 | 26.975 | Fixed Code | Not compatible with HL5. |
| 7 781 999 721 | 26.975 | Fixed Code | Not compatible with HL5. |
| 7 781 999 730 | 26.975 | Fixed Code | Not compatible with HL5. |
| 7 781 999 728 | 26.995 | Fixed Code | Not compatible with HL5. |
| 7 781 999 733 | 26.995 | Fixed Code | Not compatible with HL5. |
| 7 781 999 736 | 26.995 | Fixed Code | Not compatible with HL5. |
| 7 781 999 738 | 26.995 | Fixed Code | Not compatible with HL5. |
| 7 781 999 734 | 27.145 | Fixed Code | Not compatible with HL5. |
| 8 787 025 048 | 27.145 | Fixed Code | Not compatible with HL5. |
| 7 781 999 722 | 40.68 | Fixed Code | Not compatible with HL5. |
| 7 781 999 731 | 40.68 | Fixed Code | Not compatible with HL5. |
| 7 781 999 742 | 40.68 | Fixed Code | Not compatible with HL5. |
| 7 781 999 742 | 40.68 | Fixed Code | Not compatible with HL5. |
| 7 781 999 744 | 40.68 | Fixed Code | Not compatible with HL5. |
| 7 781 999 744 | 40.68 | Fixed Code | Not compatible with HL5. |
| 7 781 999 739 | 40.685 | Fixed Code | Not compatible with HL5. |

BRANNKEMPER

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

BREDA

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|-------|
| TX03-434-4-XP | 434.42 | Rolling Code | |

BRIOTUS

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

Brix Zaun + Tor GmbH

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|------------|--------------------------|
| TTE88042 | 40.685 | Fixed Code | Not compatible with HL5. |
| TTE88043 | 40.685 | Fixed Code | Not compatible with HL5. |
| TTE88044 | 40.685 | Fixed Code | Not compatible with HL5. |
| TTE88052 | 433.92 | Fixed Code | |
| TTE88054 | 433.92 | Fixed Code | |



Compatible Device Manufacturers

If your device is not listed here, it may not be compatible with HomeLink. Don't see your device? [Get a universal receiver here.](#)

| | | | |
|----------|-------|------------|--|
| TTE88120 | 868.3 | Fixed Code | compatible since HomeLink Software Version 7 |
| TTE88140 | 868.3 | Fixed Code | compatible since HomeLink SW version 7 |

BURGERTORE

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

Came

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|------------|--------------------------|
| - | 26.995 | Fixed Code | Not compatible with HL5. |
| - | 26.995 | Fixed Code | Not compatible with HL5. |
| - | 30.9 | Fixed Code | Not compatible with HL5. |
| TOP 432M | 433.92 | Fixed Code | |
| TOP 432NA | 433.92 | Fixed Code | |
| TOP 432SA | 433.92 | Fixed Code | |
| TOP 434M | 433.92 | Fixed Code | |
| TOP 434MA | 433.92 | Fixed Code | |
| TOP 434NA | 433.92 | Fixed Code | |
| TOP432S | 433.92 | Fixed Code | |

Cardale doors

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|------------|--|
| 433-1C | 433.92 | Fixed Code | |
| 433-2C | 433.92 | Fixed Code | |
| 433-4C | 433.92 | Fixed Code | |
| 433-4C II | 433.92 | Fixed Code | |
| 433-M1C | 433.92 | Fixed Code | |
| 868-4C | 868.3 | Fixed Code | compatible since HomeLink Software Version 7 |

Cardin

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|------------|--------------------------|
| S 738 | 27.195 | Fixed Code | Not compatible with HL5. |
| S 466 TX 2 | 29.875 | Fixed Code | Not compatible with HL5. |
| S 466 TX 4 | 29.875 | Fixed Code | Not compatible with HL5. |
| S 38 TX 2 | 30.875 | Fixed Code | Not compatible with HL5. |
| S 38 TX4 | 30.875 | Fixed Code | Not compatible with HL5. |
| S 48 TX 2 | 30.875 | Fixed Code | Not compatible with HL5. |
| S 48 TX 4 | 30.875 | Fixed Code | Not compatible with HL5. |
| S 476 TX 2 | 433.92 | Fixed Code | |
| S 476 TX 4 | 433.92 | Fixed Code | |

Catnic

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|------------|--|
| G 4180 E | 418 | Fixed Code | Only compatible with vehicles built prior to 2016. |

| | | | |
|----------|--------|------------|--|
| G 4183 E | 418 | Fixed Code | Only compatible with vehicles built prior to 2016. |
| G 4330 E | 433.92 | Fixed Code | |
| G 4332 E | 433.92 | Fixed Code | |
| G 4333 E | 433.92 | Fixed Code | |

Centurion deuren

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|------------|--|
| 433-1C | 433.92 | Fixed Code | |
| 433-2C | 433.92 | Fixed Code | |
| 433-4C | 433.92 | Fixed Code | |
| 433-4C II | 433.92 | Fixed Code | |
| 433-M1C | 433.92 | Fixed Code | |
| TX433-3C | 433.92 | Fixed Code | |
| TX433-4C | 433.92 | Fixed Code | |
| 868-4C | 868.3 | Fixed Code | compatible since HomeLink Software Version 7 |
| TX868-3C | 868.3 | Fixed Code | compatible since HomeLink Software Version 7 |
| TX868-4C | 868.3 | Fixed Code | compatible since HomeLink Software Version 7 |

Chamberlain

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| 1A3231 1B | 27.145 | Fixed Code | Not compatible with HL5. |
| 1A3232 1B | 27.145 | Fixed Code | Not compatible with HL5. |
| G 750 EML | 27.145 | Fixed Code | Not compatible with HL5. |
| G 751 EML | 27.145 | Fixed Code | Not compatible with HL5. |
| G 752 EML (2B) | 27.145 | Fixed Code | Not compatible with HL5. |
| G 754 EML (4B) | 27.145 | Fixed Code | Not compatible with HL5. |
| 84335EML | 433.92 | Rolling Code | |
| G 4330 EML | 433.92 | Fixed Code | |
| G 4333 EML (3B) | 433.92 | Fixed Code | |
| G 4335 EML | 433.92 | Fixed Code | |
| G4330E | 433.92 | Fixed Code | |
| TX4RUNI | 433MHz | Rolling Code | compatible since Software version 8 |
| 98685E | 868.3 | Rolling Code | compatible since HomeLink Software Version 7 |
| TX2EV (F30A-R) | 868MHz | Rolling Code | compatible since Software version 8 |

Cierres Breogan

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

Clem SA

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|------------|-------|
| Digicode MH-1 | 433.9 | Fixed Code | |

Coalval

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

Corsaro

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

Crawford

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--------------------------|
| T102497-27-5 | 27.045 | Fixed Code | Not compatible with HL5. |
| RFKCO-40-5 | 40.685 | Fixed Code | Not compatible with HL5. |
| T102497-40-5 | 40.685 | Fixed Code | Not compatible with HL5. |
| T397-40-2 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX02-40-2 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX03-40-1/5 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX04-40-15 | 40.685 | Fixed Code | Not compatible with HL5. |
| K 022475 | 433.92 | Fixed Code | |
| K 022476 | 433.92 | Fixed Code | |
| K 022477 | 433.92 | Fixed Code | |
| T14637 | 433.92 | Rolling Code | |
| T14638 | 433.92 | Rolling Code | |

Croci

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------|-------|
| | | | |

Compatible Device Manufacturers

If your device is not listed here, it may not be compatible with HomeLink. Don't see your device? [Get a universal receiver here.](#)

| | | | |
|------------|--------|------------|--|
| RADIO.TX.2 | 433.92 | Fixed Code | |
| TRASM 1 | 433.92 | Fixed Code | |
| SF-TRASM | 868.3 | Fixed Code | compatible since HomeLink Software Version 7 |

CWI Electrotechnics

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|------------|-------|
| HE4331 | 433.92 | Fixed Code | |

Dandler

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

Delma

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| BAME-MIZAR | 433.92 | Fixed Code | compatible since Software version 7 |
| DIP-ROL-COPY | 433.92 | Rolling Code | only 4 buttons grey version compatible |
| Joy | 433.92 | Rolling Code | compatible since HomeLink Software Version 7 |
| King 2 | 433.92 | Fixed Code | |
| King 4 | 433.92 | Fixed Code | |

Dickert

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|-------------------------------------|
| AHS27... | 27.015 | Fixed Code | Not compatible with HL5. |
| DX27... | 27.015 | Fixed Code | Not compatible with HL5. |
| MAHS27... | 27.015 | Fixed Code | Not compatible with HL5. |
| AHS40... | 40.685 | Fixed Code | Not compatible with HL5. |
| DX40... | 40.685 | Fixed Code | Not compatible with HL5. |
| IAMS40 | 40.685 | Fixed Code | Not compatible with HL5. |
| IFMS20 | 40.685 | Fixed Code | Not compatible with HL5. |
| MAHS40... | 40.685 | Fixed Code | Not compatible with HL5. |
| IAMS-433... | 433.92 | Fixed Code | |
| IS-433... | 433.92 | Fixed Code | |
| MAHS433... | 433.92 | Fixed Code | |
| S10-433A...L... | 433.92 | Fixed Code | |
| S10-433A1K00 | 433.92 | Rolling Code | compatible since Software version 7 |
| S10-433A4K00 | 433.92 | Rolling Code | compatible since Software version 7 |
| S20-433A...L... | 433.92 | Fixed Code | |
| S20-433A1K00 | 433.92 | Rolling Code | compatible since Software version 7 |
| S20-433A4K00 | 433.92 | Rolling Code | compatible since Software version 7 |
| S5-433A...L... | 433.92 | Fixed Code | |

Compatible Device Manufacturers

If your device is not listed here, it may not be compatible with HomeLink. Don't see your device? [Get a universal receiver here.](#)

| | | | |
|-----------------|--------|--------------|--|
| S5-433A2K00 | 433.92 | Rolling Code | compatible since Software version 7 |
| S8Q-433A15K00 | 433.92 | Rolling Code | compatible since Software version 7 |
| S8Q-433A15L00 | 433.92 | Fixed Code | compatible since Software version 7 |
| HS868A...L... | 868.3 | Fixed Code | compatible since HomeLink Software Version 7 |
| IS-868 | 868.3 | Fixed Code | compatible since HomeLink Software Version 7 |
| S10-868A...L... | 868.3 | Fixed Code | compatible since HomeLink Software Version 7 |
| S20-868A...L... | 868.3 | Fixed Code | compatible since HomeLink Software Version 7 |
| S5-868A...L... | 868.3 | Fixed Code | compatible since HomeLink Software Version 7 |
| HS868-00 | 868.30 | Rolling Code | compatible since Software version 7 |
| S10-868A1K00 | 868.30 | Rolling Code | compatible since Software version 7 |
| S10-868A4K00 | 868.30 | Rolling Code | compatible since Software version 7 |
| S20-868A1K00 | 868.30 | Rolling Code | compatible since Software version 7 |
| S20-868A4K00 | 868.30 | Rolling Code | compatible since Software version 7 |
| S5-868A2K00 | 868.30 | Rolling Code | compatible since Software version 7 |
| S8Q-868A15K00 | 868.30 | Rolling Code | compatible since Software version 7 |
| S8Q-868A15L00 | 868.30 | Fixed Code | compatible since Software version 7 |

Diplomat

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|------------|-------|
| 433-1C | 433.92 | Fixed Code | |
| 433-2C | 433.92 | Fixed Code | |
| 433-4C | 433.92 | Fixed Code | |
| 433-4C II | 433.92 | Fixed Code | |
| 433-M1C | 433.92 | Fixed Code | |
| TX433-3C | 433.92 | Fixed Code | |
| TX433-4C | 433.92 | Fixed Code | |

Diplomatdoerrar

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|------------|--|
| 433-1C | 433.92 | Fixed Code | |
| 433-2C | 433.92 | Fixed Code | |
| 433-4C | 433.92 | Fixed Code | |
| 433-4C II | 433.92 | Fixed Code | |
| 433-M1C | 433.92 | Fixed Code | |
| TX433-3C | 433.92 | Fixed Code | |
| TX433-4C | 433.92 | Fixed Code | |
| 868-4C | 868.3 | Fixed Code | compatible since HomeLink Software Version 7 |

Ditec

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--------------------------|
| BIXAG4 | 40.685 | Rolling Code | Not compatible with HL5. |
| BIXLG4 | 433.92 | Rolling Code | |
| BIXLP2 | 433.92 | Rolling Code | |
| BIXLS2 | 433.92 | Rolling Code | |

Domoferm

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|------------|--------------------------|
| T102497-40-5 | 40.685 | Fixed Code | Not compatible with HL5. |
| T397-40-2 | 40.685 | Fixed Code | Not compatible with HL5. |

Doormaster

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|------------|--------------------------|
| G750ED | 27.145 | Fixed Code | Not compatible with HL5. |
| G751ED | 27.145 | Fixed Code | Not compatible with HL5. |
| G4330ED | 433.92 | Fixed Code | |

Dortech

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|----------------------|-----------------|------------|--|
| Digital 101 | 27.045 | Fixed Code | Not compatible with HL5. |
| Digital 211 | 433.92 | Fixed Code | |
| Digital 212 | 433.92 | Fixed Code | |
| Digital 214 | 433.92 | Fixed Code | |
| Digital 302 / 64 173 | 868.3 | Fixed Code | compatible since HomeLink Software Version 7 |

Compatible Device Manufacturers

If your device is not listed here, it may not be compatible with HomeLink. Don't see your device? [Get a universal receiver here.](#)

| | | | |
|----------------------|-------|------------|--|
| Digital 304 / 64 037 | 868.3 | Fixed Code | compatible since HomeLink Software Version 7 |
| Digital 313 / 64 180 | 868.3 | Fixed Code | compatible since HomeLink Software Version 7 |

Droessler

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

DTM System

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|-------------------------------------|
| DTM 433MHz | 433MHz | Rolling Code | compatible since Software version 8 |

E-King

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|------------|--|
| 433-1C | 433.92 | Fixed Code | |
| 433-2C | 433.92 | Fixed Code | |
| 433-4C | 433.92 | Fixed Code | |
| 433-4C II | 433.92 | Fixed Code | |
| 433-M1C | 433.92 | Fixed Code | |
| TX433-3C | 433.92 | Fixed Code | |
| TX433-4C | 433.92 | Fixed Code | |
| 868-4C | 868.3 | Fixed Code | compatible since HomeLink Software Version 7 |
| TX868-3C | 868.3 | Fixed Code | compatible since HomeLink Software Version 7 |
| TX868-4C | 868.3 | Fixed Code | compatible since HomeLink Software Version 7 |

easy-tec / door-tec

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|------------|--|
| 1 KHS DX27 | 27.015 | Fixed Code | Not compatible with HL5. |
| 2 KHS DX27 | 27.015 | Fixed Code | Not compatible with HL5. |
| 3 KHS DX27 | 27.015 | Fixed Code | Not compatible with HL5. |
| 4 KHS DX27 | 27.015 | Fixed Code | Not compatible with HL5. |
| LW27/40BS4N | 27.015 | Fixed Code | Not compatible with HL5. |
| LW40 MS3/4 | 27.015 | Fixed Code | Not compatible with HL5. |
| BIO | 30.875 | Fixed Code | Not compatible with HL5. |
| K | 30.875 | Fixed Code | Not compatible with HL5. |
| 1 KHS DX40 | 40.685 | Fixed Code | Not compatible with HL5. |
| 1K FHS | 40.685 | Fixed Code | Not compatible with HL5. |
| 1K FHS20 | 40.685 | Fixed Code | Not compatible with HL5. |
| 2 KHS DX40 | 40.685 | Fixed Code | Not compatible with HL5. |
| 3 KHS DX40 | 40.685 | Fixed Code | Not compatible with HL5. |
| 4 KHS DX40 | 40.685 | Fixed Code | Not compatible with HL5. |
| 40HS98K/U | 40.685 | Fixed Code | Not compatible with HL5.Red buttons are not compatible |
| 40MIU/IK | 40.685 | Fixed Code | Not compatible with HL5.Red buttons are not compatible |
| 40MS3/4 | 40.685 | Fixed Code | Not compatible with HL5.Red buttons are not compatible |
| 4K FHS | 40.685 | Fixed Code | Not compatible with HL5. |
| 4K FHS20 | 40.685 | Fixed Code | Not compatible with HL5. |
| MS4099U/K | 40.685 | Fixed Code | Not compatible with HL5.Red buttons are not compatible |

| | | | |
|----------------|---------|--------------|--|
| LW433HS98FU/FK | 433.92 | Fixed Code | |
| LW433MS2 | 433.92 | Fixed Code | |
| NEO1 | 433.92 | Rolling Code | |
| NEO2 | 433.92 | Rolling Code | |
| NEO4 | 433.92 | Rolling Code | |
| SKX2 .. | 433.975 | Fixed Code | |
| SKX3 .. | 433.975 | Fixed Code | |
| SKX4 .. | 433.975 | Fixed Code | |

Eazymatic

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|--------------------|-----------------|------------|-------------------------------------|
| HS-HF 20.214 (DCL) | 433.92 | Fixed Code | compatible since Software version 8 |
| HS-HF 20.218 (DCL) | 868.30 | Fixed Code | compatible since Software version 8 |

ECILA

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

EcoStar

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--------------------------|
| Ecostar 2 | 40.685 | Fixed Code | Not compatible with HL5. |
| EcoStar4 | 40.685 | Fixed Code | Not compatible with HL5. |
| RCT3b-433 | 433.92 | Rolling Code | |
| RSC2-433 | 433.92 | Rolling Code | |
| RSE2-433 | 433.92 | Rolling Code | |
| RSZ1-433 | 433.92 | Rolling Code | |

Einhell

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|------------|--------------------------|
| - | 26.995 | Fixed Code | Not compatible with HL5. |
| F1024/1 | 26.995 | Fixed Code | Not compatible with HL5. |
| HS 434/6 | 434.07 | Fixed Code | |

Eisen-Fischer

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------|-------|
|------------------|-----------------|--------|-------|

| | | | |
|------------|-------|--------------|--|
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |
|------------|-------|--------------|--|

Eldat

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|------------|--|
| FHS 06-1 | 433.92 | Fixed Code | |
| FHS 06-2 | 433.92 | Fixed Code | |
| FHS 06-4 | 433.92 | Fixed Code | |
| FHS 20-3 | 433.92 | Fixed Code | |
| FHS 20-4 | 433.92 | Fixed Code | |
| FHS 21-1 | 433.92 | Fixed Code | |
| FHS 21-2 | 433.92 | Fixed Code | |
| RT20 | 868.3 | Fixed Code | compatible since HomeLink Software Version 7 |
| RT21 | 868.3 | Fixed Code | compatible since HomeLink Software Version 7 |

Electrolift

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

Elero

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| RFKCO-40-5 | 40.685 | Fixed Code | Not compatible with HL5. |
| T102497-40-5 | 40.685 | Fixed Code | Not compatible with HL5. |
| T397-40-2 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX02-40-2 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX03-40-1/5 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX04-40-15 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX03-8-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

Elka

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|------------|--------------------------|
| SM 1 | 26.985 | Fixed Code | Not compatible with HL5. |
| SKX 1LC | 433.975 | Fixed Code | |

Compatible Device Manufacturers

If your device is not listed here, it may not be compatible with HomeLink. Don't see your device? [Get a universal receiver here.](#)

| | | | |
|-------|-----|------------|--|
| SK 1 | 434 | Fixed Code | |
| SK 2 | 434 | Fixed Code | |
| SK 3 | 434 | Fixed Code | |
| SK 4 | 434 | Fixed Code | |
| SKI 1 | 434 | Fixed Code | |
| SKI 2 | 434 | Fixed Code | |
| SKI 3 | 434 | Fixed Code | |
| SKI 4 | 434 | Fixed Code | |
| SKJ 2 | 434 | Fixed Code | |
| SKX 1 | 434 | Fixed Code | |
| SKX 2 | 434 | Fixed Code | |
| SKX 3 | 434 | Fixed Code | |
| SKX 4 | 434 | Fixed Code | |

Elletrab

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|------------|-------|
| - | 433.92 | Fixed Code | |

ELOB

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

Els0

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|------------|--|
| RT 20 | 868.3 | Fixed Code | compatible since HomeLink Software Version 7 |
| RT 21 | 868.3 | Fixed Code | compatible since HomeLink Software Version 7 |

Emutec

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

EOS

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|------------|--------------------------|
| RFKCO-40-5 | 40.685 | Fixed Code | Not compatible with HL5. |

| | | | |
|--------------|--------|------------|--------------------------|
| T102497-40-5 | 40.685 | Fixed Code | Not compatible with HL5. |
| T397-40-2 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX02-40-2 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX03-40-1/5 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX04-40-15 | 40.685 | Fixed Code | Not compatible with HL5. |

Erreka

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|------------|--------------------------|
| RFKCO-40-5 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX02-40-2 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX03-40-1/5 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX04-40-15 | 40.685 | Fixed Code | Not compatible with HL5. |
| RES1 N09 | 433.92 | Fixed Code | |
| RES2 N09 | 433.92 | Fixed Code | |

ES-Tore

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|------------|--------------------------|
| T102497-40-5 | 40.685 | Fixed Code | Not compatible with HL5. |
| T397-40-2 | 40.685 | Fixed Code | Not compatible with HL5. |

Espace Della Vecchia

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

ETT 2 TRE

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

Europe Doors

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|------------|--|
| 433-4C II | 433.92 | Fixed Code | compatible since HomeLink Software Version 7 |
| 868-4C | 868.3 | Fixed Code | compatible since HomeLink Software Version 7 |
| TX868-3C | 868.3 | Fixed Code | compatible since HomeLink Software Version 7 |



Compatible Device Manufacturers

If your device is not listed here, it may not be compatible with HomeLink. Don't see your device? [Get a universal receiver here.](#)

| | | | |
|-----------|-------|------------|--|
| TX868-4C | 868.3 | Fixed Code | compatible since HomeLink Software Version 7 |
| TXM868-2C | 868.3 | Fixed Code | compatible since HomeLink Software Version 7 |

Everest

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|-------|
| 1K AM HS | 433.92 | Rolling Code | |
| 4K AM HS | 433.92 | Rolling Code | |

F.A.M.E.

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

FAAC

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|------------|--|
| DH 02 | 26.975 | Fixed Code | Not compatible with HL5. |
| DH 03 | 26.975 | Fixed Code | Not compatible with HL5. |
| DH 04 | 26.975 | Fixed Code | Not compatible with HL5. |
| 27 DS | 27 | Fixed Code | Not compatible with HL5. |
| 31 DS | 30.875 | Fixed Code | Not compatible with HL5. |
| EcoStar 2 | 40.685 | Fixed Code | Not compatible with HL5. |
| EcoStar 4 | 40.685 | Fixed Code | Not compatible with HL5. |
| FCT10 | 40.685 | Fixed Code | Not compatible with HL5. |
| HS16 | 40.685 | Fixed Code | Not compatible with HL5. |
| HS2 | 40.685 | Fixed Code | Not compatible with HL5. |
| HS4 | 40.685 | Fixed Code | Not compatible with HL5. |
| HSE2 | 40.685 | Fixed Code | Not compatible with HL5. |
| HSM2 | 40.685 | Fixed Code | Not compatible with HL5. |
| HSM4 | 40.685 | Fixed Code | Not compatible with HL5. |
| TMN 40SL | 40.685 | Fixed Code | Not compatible with HL5. |
| 418 SL | 418 | Fixed Code | Only compatible with vehicles built prior to 2016. |
| RS2 | 433.92 | Fixed Code | |
| RS4 | 433.92 | Fixed Code | |
| RSE2 | 433.92 | Fixed Code | |
| RSM2 | 433.92 | Fixed Code | |
| RSM4 | 433.92 | Fixed Code | |
| TM1 433 DS | 433.92 | Fixed Code | |
| TM2 433 DS | 433.92 | Fixed Code | |
| TM2 433 ESL | 433.92 | Fixed Code | |
| TM3 433 DS | 433.92 | Fixed Code | |
| TM4 433 ESL | 433.92 | Fixed Code | |

Falken-Tore

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

Feig

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

Feldmann

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

FINCHIUSURE

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|-------|
| TX03-434-4-XP | 434.42 | Rolling Code | |

France Fermeture

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

Garador

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--------------------------|
| DH 01 | 26.975 | Fixed Code | Not compatible with HL5. |
| DH 02 | 26.975 | Fixed Code | Not compatible with HL5. |
| DH 03 | 26.975 | Fixed Code | Not compatible with HL5. |
| DH 04 | 26.975 | Fixed Code | Not compatible with HL5. |
| EcoStar 2 | 40.685 | Fixed Code | Not compatible with HL5. |
| EcoStar 4 | 40.685 | Fixed Code | Not compatible with HL5. |
| FCT10 | 40.685 | Fixed Code | Not compatible with HL5. |
| HS16 | 40.685 | Fixed Code | Not compatible with HL5. |
| HS2 | 40.685 | Fixed Code | Not compatible with HL5. |
| HS4 | 40.685 | Fixed Code | Not compatible with HL5. |
| HSE2 | 40.685 | Fixed Code | Not compatible with HL5. |
| HSM2 | 40.685 | Fixed Code | Not compatible with HL5. |
| HSM4 | 40.685 | Fixed Code | Not compatible with HL5. |
| RS2 | 433.92 | Rolling Code | |
| RS4 | 433.92 | Rolling Code | |
| RSE2 | 433.92 | Rolling Code | |
| RSM2 | 433.92 | Rolling Code | |
| RSM4 | 433.92 | Rolling Code | |

Garageportexperten

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

Garog

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|------------|--------------------------|
| S466 | 26.995 | Fixed Code | Not compatible with HL5. |

Gausemeier

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

GEBA

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|------------|-------|
| RCA T4SP 433 | 433.92 | Fixed Code | |

GFA-Elektromaten

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|------------|--------------------------|
| M 512 | 26.985 | Fixed Code | Not compatible with HL5. |
| K 512 | 433.92 | Fixed Code | |

GiBiDi

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| Arm AU01530 | 30.875 | Fixed Code | Not compatible with HL5. |
| Arm AU01540 | 30.875 | Fixed Code | Not compatible with HL5. |
| Open 70200 | 433.92 | Fixed Code | |
| Open 70201 | 433.92 | Fixed Code | |
| Roller AU01590 | 433.92 | Rolling Code | compatible since HomeLink Software Version 7 |
| Roller AU01600 | 433.92 | Rolling Code | compatible since HomeLink Software Version 7 |
| Roller AU01610 | 433.92 | Rolling Code | compatible since HomeLink Software Version 7 |
| Roller AU01680 | 433.92 | Rolling Code | compatible since HomeLink Software Version 7 |
| Roller AU01800 | 433.92 | Rolling Code | compatible since HomeLink Software Version 7 |
| Roller AU01810 | 433.92 | Rolling Code | compatible since HomeLink Software Version 7 |

Gilgen Door Systems AG

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|-----------------------|-----------------|------------|--|
| BE40L | 40.685 | Fixed Code | Not compatible with HL5. |
| RFKCO-40-5 | 40.685 | Fixed Code | Not compatible with HL5. |
| T397-40-2 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX02-40-2 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX03-40-1/5 | 40.685 | Fixed Code | Not compatible with HL5. |
| F7000-S2 | 433.92 | Fixed Code | compatible since HomeLink Software Version 7 |
| SFG2KG / Funk 9000 S2 | 868.3 | Fixed Code | compatible since HomeLink Software Version 7 |
| SFG4KG / Funk 9000 S4 | 868.3 | Fixed Code | compatible since HomeLink Software Version 7 |
| F9000 S4 | 868.45 | Fixed Code | compatible since HomeLink Software Version 7 |

| | | | |
|-------|--------|------------|--|
| GFU 4 | 868.45 | Fixed Code | compatible since HomeLink Software Version 7 |
|-------|--------|------------|--|

Gobbato

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| RAD/B1S | 433.92 | Fixed Code | |
| RAD/B2S | 433.92 | Fixed Code | |
| Tra2s | 433.92 | Rolling Code | compatible since HomeLink Software Version 7 |
| Tra3s | 433.92 | Rolling Code | compatible since HomeLink Software Version 7 |

Goetzfried

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

Groen + Jansen

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

Groetz

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| T102497-40-5 | 40.685 | Fixed Code | Not compatible with HL5. |
| T397-40-2 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

Guckelsberger Waldbrunn

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

Guenther

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------|-------|
| | | | |

Compatible Device Manufacturers

If your device is not listed here, it may not be compatible with HomeLink. Don't see your device? [Get a universal receiver here.](#)

| | | | |
|--------------|--------|--------------|--|
| T102497-40-5 | 40.685 | Fixed Code | Not compatible with HL5. |
| T397-40-2 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

Guttomat

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

GVK

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

Gypass

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

Hacker

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--------------------------|
| 27AM | 26.995 | Fixed Code | Not compatible with HL5. |
| 40AM | 40.685 | Fixed Code | Not compatible with HL5. |
| 40FM | 40.685 | Fixed Code | Not compatible with HL5. |
| SKR 433 | 433.92 | Rolling Code | |
| SKRJ 433 | 433.92 | Rolling Code | |

Hees + Peters

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

Heinzmann

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| 657100 | 868.3 | Fixed Code | compatible since HomeLink Software Version 7 |
| 657110 | 868.3 | Fixed Code | compatible since HomeLink Software Version 7 |
| 657132 | 868.3 | Fixed Code | compatible since HomeLink Software Version 7 |
| 656600 | 868.5 | Rolling Code | compatible since HomeLink Software Version 7 |
| 656632 | 868.5 | Rolling Code | compatible since HomeLink Software Version 7 |

Henderson

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| T102497-27-5 | 27.045 | Fixed Code | Not compatible with HL5. |
| RFKCO-40-5 | 40.685 | Fixed Code | Not compatible with HL5. |
| T102497-27-5 | 40.685 | Fixed Code | Not compatible with HL5. |
| T102497-40-5 | 40.685 | Fixed Code | Not compatible with HL5. |
| T397-40-2 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX02-40-2 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX03-40-1/5 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX04-40-15 | 40.685 | Fixed Code | Not compatible with HL5. |
| 4K AM HS | 433.92 | Rolling Code | |
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

Heroal

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| RFKCO-40-5 | 40.685 | Fixed Code | Not compatible with HL5. |
| T102497-40-5 | 40.685 | Fixed Code | Not compatible with HL5. |
| T397-40-2 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX02-40-2 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX03-40-1/5 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX04-40-15 | 40.685 | Fixed Code | Not compatible with HL5. |
| Pocket 1/4 | 433.92 | Rolling Code | compatible since HomeLink Software Version 7 |
| Pocket-1K | 433.92 | Fixed Code | |
| Pocket-2K | 433.92 | Fixed Code | |
| Pocket-4K | 433.92 | Fixed Code | |
| S3-4 | 433.92 | Fixed Code | |
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

Hild-Tortechnik

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| T102497-40-5 | 40.685 | Fixed Code | Not compatible with HL5. |
| T397-40-2 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

HL Torbau

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|------------|--------------------------|
| RFKCO-40-5 | 40.685 | Fixed Code | Not compatible with HL5. |
| T102497-40-5 | 40.685 | Fixed Code | Not compatible with HL5. |
| T397-40-2 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX02-40-2 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX03-40-1/5 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX04-40-15 | 40.685 | Fixed Code | Not compatible with HL5. |

Hochtief

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|------------|--------------------------|
| T102497-40-5 | 40.685 | Fixed Code | Not compatible with HL5. |
| T397-40-2 | 40.685 | Fixed Code | Not compatible with HL5. |

Hofbauer

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

Holder

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| RFKCO-40-5 | 40.685 | Fixed Code | Not compatible with HL5. |
| T102497-40-5 | 40.685 | Fixed Code | Not compatible with HL5. |
| T397-40-2 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX02-40-2 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX03-40-1/5 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX04-40-15 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

Homentry

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|------------|-------|
| HE4331 | 433.92 | Fixed Code | |

Huth

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| T102497-40-5 | 40.685 | Fixed Code | Not compatible with HL5. |
| T397-40-2 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

HUTYRA

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

Hörmann

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|------------|--|
| DH 01 | 26.975 | Fixed Code | Not compatible with HL5. Valid for transmitters with green buttons |

Compatible Device Manufacturers

If your device is not listed here, it may not be compatible with HomeLink. Don't see your device? [Get a universal receiver here.](#)

| | | | |
|-------------|--------|--------------|--|
| DH 02 | 26.975 | Fixed Code | Not compatible with HL5. Valid for transmitters with green buttons |
| DH 03 | 26.975 | Fixed Code | Not compatible with HL5. Valid for transmitters with green buttons |
| DH 04 | 26.975 | Fixed Code | Not compatible with HL5. Valid for transmitters with green buttons |
| HSM2-26.975 | 26.975 | Fixed Code | Not compatible with HL5. Valid for transmitters with green buttons |
| HSM4-26.975 | 26.975 | Fixed Code | Not compatible with HL5. Valid for transmitters with green buttons |
| FCT10b-40 | 40.685 | Fixed Code | Not compatible with HL5. |
| HS16-40 | 40.685 | Fixed Code | Not compatible with HL5. |
| HS2-40 | 40.685 | Fixed Code | Not compatible with HL5. Valid for transmitters with grey buttons |
| HS4-40 | 40.685 | Fixed Code | Not compatible with HL5. Valid for transmitters with grey buttons |
| HSE2-40 | 40.685 | Fixed Code | Not compatible with HL5. Valid for transmitters with grey buttons |
| HSM2-40 | 40.685 | Fixed Code | Not compatible with HL5. Valid for transmitters with grey buttons |
| HSM4-40 | 40.685 | Fixed Code | Not compatible with HL5. Valid for transmitters with grey buttons |
| S850 | 40.685 | Fixed Code | Not compatible with HL5. Valid for transmitters with grey buttons |
| RCT3b-433 | 433.92 | Rolling Code | |
| RS2-433 | 433.92 | Rolling Code | Valid for transmitters with yellow buttons |
| RS4-433 | 433.92 | Rolling Code | Valid for transmitters with yellow buttons |
| RSM2-433 | 433.92 | Rolling Code | Valid for transmitters with yellow buttons |
| RSM4-433 | 433.92 | Rolling Code | Valid for transmitters with yellow buttons |

Compatible Device Manufacturers

If your device is not listed here, it may not be compatible with HomeLink. Don't see your device? [Get a universal receiver here.](#)

| | | | |
|------------|-------|------------|--|
| FCT10b-868 | 868.3 | Fixed Code | compatible since HomeLink Software Version 7 |
| FCT3b-868 | 868.3 | Fixed Code | compatible since HomeLink Software Version 7 |
| FFL12-868 | 868.3 | Fixed Code | compatible since HomeLink Software Version 7 |
| FIT2-868 | 868.3 | Fixed Code | compatible since HomeLink Software Version 7 |
| HS1-868 | 868.3 | Fixed Code | Valid for transmitters with blue buttons compatible since HomeLink Software Version 7 |
| HS16-868 | 868.3 | Fixed Code | compatible since HomeLink Software Version 7 |
| HS2-868 | 868.3 | Fixed Code | Valid for transmitters with blue buttons compatible since HomeLink Software Version 7 |
| HS4-868 | 868.3 | Fixed Code | Valid for transmitters with blue buttons compatible since HomeLink Software Version 7 |
| HSD2-868 | 868.3 | Fixed Code | compatible since HomeLink Software Version 7 |
| HSE2-868 | 868.3 | Fixed Code | Valid for transmitters with blue buttons compatible since HomeLink Software Version 7 |
| HSI-868 | 868.3 | Fixed Code | compatible since HomeLink Software Version 7 |
| HSM2-868 | 868.3 | Fixed Code | Valid for transmitters with blue buttons compatible since HomeLink Software Version 7 |
| HSM4-868 | 868.3 | Fixed Code | Valid for transmitters with blue buttons compatible since HomeLink Software Version 7 |
| HSP4-868 | 868.3 | Fixed Code | Valid for transmitters with blue buttons compatible since HomeLink Software Version 7 |
| HSP4-C-868 | 868.3 | Fixed Code | compatible since HomeLink Software Version 7 |



Compatible Device Manufacturers

If your device is not listed here, it may not be compatible with HomeLink. Don't see your device? [Get a universal receiver here.](#)

| | | | |
|----------|-------|------------|--|
| HSZ1-868 | 868.3 | Fixed Code | compatible since HomeLink Software Version 7 |
| HSZ2-868 | 868.3 | Fixed Code | compatible since HomeLink Software Version 7 |

Imexal

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

Inova

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|------------|--------------------------|
| INOVA 27 4k | 27.015 | Fixed Code | Not compatible with HL5. |
| INOVA 40 4k | 40.685 | Fixed Code | Not compatible with HL5. |
| INOVA 433 2K | 433.92 | Fixed Code | |
| INOVA 433 4k | 433.92 | Fixed Code | |
| INOVA 434 1k | 433.92 | Fixed Code | |
| INOVA 434 4k | 433.92 | Fixed Code | |

Intertechno

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|------------|-------|
| YCT-99 | 433.92 | Fixed Code | |

ISEA

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

JCM-tech

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|-------|
| NEO1 | 433.92 | Rolling Code | |
| NEO2 | 433.92 | Rolling Code | |
| NEO4 | 433.92 | Rolling Code | |

JM

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

JP Weimann

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

JP. Bensheim

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

K-Plus

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| T102497-40-5 | 40.685 | Fixed Code | Not compatible with HL5. |
| T397-40-2 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

KACKER

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

Kesting

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

Key Automation

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| TXB-42 | 433.92 | Fixed Code | |
| TXB-42R | 433.92 | Rolling Code | compatible since HomeLink Software Version 7 |
| TXG-44 | 433.92 | Fixed Code | |
| TXP-42 | 433.92 | Fixed Code | |
| TXP-42N | 433.92 | Fixed Code | |
| TXP-42R | 433.92 | Rolling Code | compatible since HomeLink Software Version 7 |

Knies

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

Koestner

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|------------|--------------------------|
| RFKCO-40-5 | 40.685 | Fixed Code | Not compatible with HL5. |

| | | | |
|--------------|--------|--------------|--|
| T102497-40-5 | 40.685 | Fixed Code | Not compatible with HL5. |
| T397-40-2 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX02-40-2 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX03-40-1/5 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX04-40-15 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

Komilfo I

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

Kottmair & Hatef

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| RFKCO-40-5 | 40.685 | Fixed Code | Not compatible with HL5. |
| T102497-40-5 | 40.685 | Fixed Code | Not compatible with HL5. |
| T397-40-2 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX02-40-2 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX03-40-1/5 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX04-40-15 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

Kreiller

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| RFKCO-40-5 | 40.685 | Fixed Code | Not compatible with HL5. |
| T102497-40-5 | 40.685 | Fixed Code | Not compatible with HL5. |
| T397-40-2 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX02-40-2 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX03-40-1/5 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX04-40-15 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

La Toulousaine

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

Lakal

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|------------|--------------------------|
| T102497-40-5 | 40.685 | Fixed Code | Not compatible with HL5. |
| T397-40-2 | 40.685 | Fixed Code | Not compatible with HL5. |

Lawiczak

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

Layh

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| RFKCO-40-5 | 40.685 | Fixed Code | Not compatible with HL5. |
| T102497-40-5 | 40.685 | Fixed Code | Not compatible with HL5. |
| T397-40-2 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX02-40-2 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX03-40-1/5 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

LEEB

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

LEPINARD

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

Lift-Master

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| 1A3531 | 27.145 | Fixed Code | Not compatible with HL5. |
| 750E | 27.145 | Fixed Code | Not compatible with HL5. |
| G3156 | 27.145 | Fixed Code | Not compatible with HL5. |
| G3271E(1B) | 27.145 | Fixed Code | Not compatible with HL5. |
| G3272E | 27.145 | Fixed Code | Not compatible with HL5. |
| G750EML | 27.145 | Fixed Code | Not compatible with HL5. |
| G751EML | 27.145 | Fixed Code | Not compatible with HL5. |
| G752EML(2B) | 27.145 | Fixed Code | Not compatible with HL5. |
| G754EML(4B) | 27.145 | Fixed Code | Not compatible with HL5. |
| 1A3570 | 40.685 | Fixed Code | Not compatible with HL5. |
| G 4180 EML | 418 | Fixed Code | Only compatible with vehicles built prior to 2016. |
| G 4183 E | 418 | Fixed Code | Only compatible with vehicles built prior to 2016. |
| G 4185 E | 418 | Fixed Code | Only compatible with vehicles built prior to 2016. |
| 94335E | 433.92 | Rolling Code | |
| G 4330 E | 433.92 | Fixed Code | |
| G 4332 E (2B) | 433.92 | Fixed Code | |
| G 4333 E (3B) | 433.92 | Fixed Code | |
| G 4335 E | 433.92 | Fixed Code | |
| TX4RUNI | 433MHz | Rolling Code | compatible since Software version 8 |
| TX4RUNI | 433MHz | Rolling Code | compatible since Software version 8 |
| TX4RUNI | 433MHz | Rolling Code | compatible since Software version 8 |
| 98685E | 868.3 | Rolling Code | compatible since HomeLink Software Version 7 |
| TX2EV (F30A-R) | 868MHz | Rolling Code | compatible since Software version 8 |

Lindpointner Torbau

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| RFKCO-40-5 | 40.685 | Fixed Code | Not compatible with HL5. |
| T102497-40-5 | 40.685 | Fixed Code | Not compatible with HL5. |
| T397-40-2 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX02-40-2 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX03-40-1/5 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX04-40-15 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

Marantec

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|----------------------|-----------------|------------|--|
| Digital 101 | 27.045 | Fixed Code | Not compatible with HL5. |
| Digital 211 | 433.92 | Fixed Code | |
| Digital 212 | 433.92 | Fixed Code | |
| Digital 214 | 433.92 | Fixed Code | |
| Digital 302 / 64 176 | 433.92 | Fixed Code | |
| Digital 304 / 64 133 | 433.92 | Fixed Code | |
| Digital 313 / 64 183 | 433.92 | Fixed Code | |
| Digital 313 / 76 955 | 433.92 | Fixed Code | |
| Digital 302 / 64 173 | 868.3 | Fixed Code | compatible since HomeLink Software Version 7 |
| Digital 304 / 64 037 | 868.3 | Fixed Code | compatible since HomeLink Software Version 7 |
| Digital 313 / 64 180 | 868.3 | Fixed Code | compatible since HomeLink Software Version 7 |
| Digital 313 / 76 852 | 868.3 | Fixed Code | compatible since HomeLink Software Version 7 |
| Digital 304 / 67 522 | 868.6 | Fixed Code | compatible since HomeLink Software Version 7 |
| Digital 311 / 72 747 | 868.6 | Fixed Code | compatible since HomeLink Software Version 7 |
| Digital 314 / 72 748 | 868.6 | Fixed Code | compatible since HomeLink Software Version 7 |

Matex Deuren

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

Meier

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| T102497-40-5 | 40.685 | Fixed Code | Not compatible with HL5. |
| T397-40-2 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX02-40-2 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX03-40-1/5 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX04-40-15 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

Meissner

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|------------|-------|
| Pocket-1/4 | 433.92 | Fixed Code | |

Memminger Torbau

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| RFKCO-40-5 | 40.685 | Fixed Code | Not compatible with HL5. |
| T102497-40-5 | 40.685 | Fixed Code | Not compatible with HL5. |
| T397-40-2 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX02-40-2 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX03-40-1/5 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX04-40-15 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

Menz-Holz

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

Merlin

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--------------------------|
| M872 | 27.145 | Fixed Code | Not compatible with HL5. |
| M874 | 27.145 | Fixed Code | Not compatible with HL5. |
| M802 | 40.685 | Fixed Code | Not compatible with HL5. |
| M804 | 40.685 | Fixed Code | Not compatible with HL5. |
| M832 | 433.92 | Rolling Code | |
| M834 | 433.92 | Rolling Code | |
| M842 | 433.92 | Rolling Code | |
| M844 | 433.92 | Rolling Code | |

Mewald

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|------------|--------------------------|
| G750E | 27.145 | Fixed Code | Not compatible with HL5. |
| G751E | 27.145 | Fixed Code | Not compatible with HL5. |
| G752E | 27.145 | Fixed Code | Not compatible with HL5. |
| G754E | 27.145 | Fixed Code | Not compatible with HL5. |
| G4330E | 433.92 | Fixed Code | |

| | | | |
|--------|--------|------------|--|
| G4333E | 433.92 | Fixed Code | |
| G4335E | 433.92 | Fixed Code | |

Mhouse

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| TX3 | 433.92 | Rolling Code | compatible since HomeLink Software Version 7 |
| TX4 | 433.92 | Rolling Code | compatible since HomeLink Software Version 7 |

Mischler

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

MITHRA

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

Mueller

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|------------|--------------------------|
| RFKCO-40-5 | 40.685 | Fixed Code | Not compatible with HL5. |
| T102497-40-5 | 40.685 | Fixed Code | Not compatible with HL5. |
| T397-40-2 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX02-40-2 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX03-40-1/5 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX04-40-15 | 40.685 | Fixed Code | Not compatible with HL5. |

MULTI CODE

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|------------|--------------------------|
| 3079-12 | 40.685 | Fixed Code | Not compatible with HL5. |

Multi Preve

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------|-------|
| | | | |



Compatible Device Manufacturers

If your device is not listed here, it may not be compatible with HomeLink. Don't see your device? [Get a universal receiver here.](#)

| | | | |
|------------|-------|--------------|--|
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |
|------------|-------|--------------|--|

Nassau Door

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|------------|--|
| 26-12498 | 868.3 | Fixed Code | compatible since HomeLink Software Version 7 |
| 26-12499 | 868.3 | Fixed Code | compatible since HomeLink Software Version 7 |
| 26-12500 | 868.3 | Fixed Code | compatible since HomeLink Software Version 7 |
| 26-12504 | 868.3 | Fixed Code | compatible since HomeLink Software Version 7 |
| 26-12507 | 868.3 | Fixed Code | compatible since HomeLink Software Version 7 |
| 26-12510 | 868.3 | Fixed Code | compatible since HomeLink Software Version 7 |

Nice

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|------------|--------------------------|
| EasyK K1 | 26.996 | Fixed Code | Not compatible with HL5. |
| EasyK K1 M | 26.996 | Fixed Code | Not compatible with HL5. |
| EasyK K12M | 26.996 | Fixed Code | Not compatible with HL5. |
| EasyK K2 | 26.996 | Fixed Code | Not compatible with HL5. |
| EasyK K2+2 | 26.996 | Fixed Code | Not compatible with HL5. |
| EasyK K4 | 26.996 | Fixed Code | Not compatible with HL5. |
| EasyK K4 M | 26.996 | Fixed Code | Not compatible with HL5. |
| Bio BT1K | 30.875 | Fixed Code | Not compatible with HL5. |
| Bio BT2K | 30.875 | Fixed Code | Not compatible with HL5. |
| Bio BT4K | 30.875 | Fixed Code | Not compatible with HL5. |
| EasyK K1 | 30.875 | Fixed Code | Not compatible with HL5. |
| EasyK K1 M | 30.875 | Fixed Code | Not compatible with HL5. |
| EasyK K12M | 30.875 | Fixed Code | Not compatible with HL5. |
| EasyK K2 | 30.875 | Fixed Code | Not compatible with HL5. |
| EasyK K2+2 | 30.875 | Fixed Code | Not compatible with HL5. |
| EasyK K4 | 30.875 | Fixed Code | Not compatible with HL5. |
| EasyK K4 M | 30.875 | Fixed Code | Not compatible with HL5. |
| Bio BT1K | 40.685 | Fixed Code | Not compatible with HL5. |
| Bio BT2K | 40.685 | Fixed Code | Not compatible with HL5. |
| Bio BT4K | 40.685 | Fixed Code | Not compatible with HL5. |
| EasyK K1 | 40.685 | Fixed Code | Not compatible with HL5. |
| EasyK K1 M | 40.685 | Fixed Code | Not compatible with HL5. |
| EasyK K12M | 40.685 | Fixed Code | Not compatible with HL5. |
| EasyK K2 | 40.685 | Fixed Code | Not compatible with HL5. |
| EasyK K2+2 | 40.685 | Fixed Code | Not compatible with HL5. |

| | | | |
|------------|--------|------------|--------------------------|
| EasyK K4 | 40.685 | Fixed Code | Not compatible with HL5. |
| EasyK K4 M | 40.685 | Fixed Code | Not compatible with HL5. |
| Flo 1 | 433.92 | Fixed Code | |
| Flo 2 | 433.92 | Fixed Code | |
| Flo 4 | 433.92 | Fixed Code | |
| Very VE | 433.92 | Fixed Code | |

Niko

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|------------|--|
| RT 20 | 868.3 | Fixed Code | compatible since HomeLink Software Version 7 |
| RT 21 | 868.3 | Fixed Code | compatible since HomeLink Software Version 7 |

Normbau

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

Normstahl/Entrematic

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|-------------------------|-----------------|--------------|-------|
| 1K AM HS | 433.92 | Rolling Code | |
| 4K AM HS | 433.92 | Rolling Code | |
| EA433-2KM Keeloq | 433.92 | Rolling Code | |
| EA433-4K Keeloq | 433.92 | Rolling Code | |
| EA433-4K Keeloq Neutral | 433.92 | Rolling Code | |
| K086957 | 433.92 | Rolling Code | |
| N000880-01-01 | 433.92 | Rolling Code | |
| N002591-0002 | 433.92 | Rolling Code | |
| N002592-00-01 | 433.92 | Rolling Code | |
| RCU433-2K Keeloq | 433.92 | Rolling Code | |
| RCU433-4K Keeloq | 433.92 | Rolling Code | |
| T14429 | 433.92 | Rolling Code | |
| T14435 | 433.92 | Rolling Code | |
| TX S5 -2C-433 MHz | 433.92 | Rolling Code | |

Novoferm

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|------------|--------------------------|
| T102497-40-5 | 40.685 | Fixed Code | Not compatible with HL5. |

| | | | |
|--------------------|--------|--------------|--|
| HS 43-1E | 433.92 | Fixed Code | |
| Micro-Novotron 312 | 433.92 | Rolling Code | |
| Micro-Novotron 512 | 433.92 | Rolling Code | |
| Mini-Novotron 302 | 433.92 | Rolling Code | |
| Mini-Novotron 304 | 433.92 | Rolling Code | |
| Mini-Novotron 401 | 433.92 | Fixed Code | |
| Mini-Novotron 404 | 433.92 | Fixed Code | |
| Mini-Novotron 502 | 433.92 | Rolling Code | |
| Mini-Novotron 504 | 433.92 | Rolling Code | |
| Novotron 202 MB | 433.92 | Fixed Code | |

Novotecnica

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|------------|--|
| BIT E1 | 26.995 | Fixed Code | Not compatible with HL5. Multiple button pushes necessary for training |
| BIT QET1 | 26.995 | Fixed Code | Not compatible with HL5. Multiple button pushes necessary for training |
| BIT QET4 | 26.995 | Fixed Code | Not compatible with HL5. Multiple button pushes necessary for training |
| BIT V1 | 30.9 | Fixed Code | Not compatible with HL5. Multiple button pushes necessary for training |
| BIT V2 | 30.9 | Fixed Code | Not compatible with HL5. Multiple button pushes necessary for training |
| BIT VT1 | 30.9 | Fixed Code | Not compatible with HL5. Multiple button pushes necessary for training |
| BIT VT4 | 30.9 | Fixed Code | Not compatible with HL5. Multiple button pushes necessary for training |
| BIX A1 | 40.685 | Fixed Code | Not compatible with HL5. Multiple button pushes necessary for training |
| BIX A2 | 40.685 | Fixed Code | Not compatible with HL5. Multiple button pushes necessary for training |
| BIX A4 | 40.685 | Fixed Code | Not compatible with HL5. Multiple button pushes necessary for training |

Compatible Device Manufacturers

If your device is not listed here, it may not be compatible with HomeLink. Don't see your device? [Get a universal receiver here.](#)

NOW

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| T102497-40-5 | 40.685 | Fixed Code | Not compatible with HL5. |
| T397-40-2 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

Compatible Device Manufacturers

If your device is not listed here, it may not be compatible with HomeLink. Don't see your device? [Get a universal receiver here.](#)

Orther

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

PAMAX

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| SF 40-.... | 40.662 | Fixed Code | Not compatible with HL5. |
| SF 40-.... | 40.662 | Fixed Code | Not compatible with HL5. |
| SF 433-... | 433.075 | Fixed Code | |
| SF 433-... | 433.075 | Fixed Code | |
| SA 434-... | 433.92 | Rolling Code | |
| SA 434-... | 433.92 | Fixed Code | |
| SA 868-... | 868.35 | Rolling Code | compatible since HomeLink Software Version 7 |
| SA 868-... | 868.35 | Rolling Code | compatible since HomeLink Software Version 7 |

Peha

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|------------|--|
| RT 20 | 868.3 | Fixed Code | compatible since HomeLink Software Version 7 |
| RT 21 | 868.3 | Fixed Code | compatible since HomeLink Software Version 7 |

Peters & Peters

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| T102497-40-5 | 40.685 | Fixed Code | Not compatible with HL5. |
| T397-40-2 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

PFT

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

Pfullendorfer

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|------------|--------------------------|
| SM1 | 26.995 | Fixed Code | Not compatible with HL5. |
| SM1MD | 26.995 | Fixed Code | Not compatible with HL5. |
| SM2 | 26.995 | Fixed Code | Not compatible with HL5. |
| SM2MD | 26.995 | Fixed Code | Not compatible with HL5. |

Compatible Device Manufacturers

If your device is not listed here, it may not be compatible with HomeLink. Don't see your device? [Get a universal receiver here.](#)

| | | | |
|---------------------|---------|------------|--|
| SM3 | 26.995 | Fixed Code | Not compatible with HL5. |
| SM3MD | 26.995 | Fixed Code | Not compatible with HL5. |
| SM4 | 26.995 | Fixed Code | Not compatible with HL5. |
| SM4MD | 26.995 | Fixed Code | Not compatible with HL5. |
| - | 433.92 | Fixed Code | |
| Digital 211 | 433.92 | Fixed Code | |
| Digital 302 / 64176 | 433.92 | Fixed Code | |
| Digital 304 / 64133 | 433.92 | Fixed Code | |
| SKX1MD | 433.92 | Fixed Code | |
| SKX2MD | 433.92 | Fixed Code | |
| SKX3MD | 433.92 | Fixed Code | |
| SKX4MD | 433.92 | Fixed Code | |
| SKJ | 433.995 | Fixed Code | |
| SKX3MD | 433.995 | Fixed Code | |
| SKX4MD | 433.995 | Fixed Code | |
| Digital 302 / 64173 | 868.3 | Fixed Code | compatible since HomeLink Software Version 7 |
| Digital 304 / 64037 | 868.3 | Fixed Code | compatible since HomeLink Software Version 7 |
| Digital 313 / 64180 | 868.3 | Fixed Code | compatible since HomeLink Software Version 7 |

Planzer

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

Pleidelsheim

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|------------|--------------------------|
| RFKCO-40-5 | 40.685 | Fixed Code | Not compatible with HL5. |
| T102497-40-5 | 40.685 | Fixed Code | Not compatible with HL5. |
| T397-40-2 | 40.685 | Fixed Code | Not compatible with HL5. |
| T397-40-2 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX02-40-2 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX03-40-1/5 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX04-40-15 | 40.685 | Fixed Code | Not compatible with HL5. |

Poellrath

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------|-------|
| | | | |

Compatible Device Manufacturers

If your device is not listed here, it may not be compatible with HomeLink. Don't see your device? [Get a universal receiver here.](#)

| | | | |
|------------|-------|--------------|--|
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |
|------------|-------|--------------|--|

Portnorma

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|-------|
| NEO1 | 433.92 | Rolling Code | |
| NEO2 | 433.92 | Rolling Code | |
| NEO4 | 433.92 | Rolling Code | |

Promotec

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

Rademacher

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--------------------------|
| 27MHz | 27.155 | Fixed Code | Not compatible with HL5. |
| 40MHz | 40.685 | Fixed Code | Not compatible with HL5. |
| 4355 | 433.92 | Rolling Code | |
| 4385 | 433.92 | Rolling Code | |

Rasselstein

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

Rauch

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| RFKCO-40-5 | 40.685 | Fixed Code | Not compatible with HL5. |
| RFKCO-40-5 | 40.685 | Fixed Code | Not compatible with HL5. |
| T102497-40-5 | 40.685 | Fixed Code | Not compatible with HL5. |
| T397-40-2 | 40.685 | Fixed Code | Not compatible with HL5. |
| T397-40-2 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX02-40-2 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX02-40-2 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX03-40-1/5 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX03-40-1/5 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX04-40-15 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX04-40-15 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

RCE

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|------------|--------------------------|
| RBL1 | 30.875 | Fixed Code | Not compatible with HL5. |
| RBL2 | 30.875 | Fixed Code | Not compatible with HL5. |
| TK1 | 30.875 | Fixed Code | Not compatible with HL5. |
| TK2 | 30.875 | Fixed Code | Not compatible with HL5. |
| TK3 | 30.875 | Fixed Code | Not compatible with HL5. |
| TK4 | 30.875 | Fixed Code | Not compatible with HL5. |
| TP1 | 30.875 | Fixed Code | Not compatible with HL5. |
| TP2 | 30.875 | Fixed Code | Not compatible with HL5. |

RDA

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|-------|
| Combi 433 | 433.92 | Fixed Code | |
| IND 01 | 433.92 | Fixed Code | |
| IND 02 | 433.92 | Fixed Code | |
| IND 04 | 433.92 | Fixed Code | |
| TWINR | 433.92 | Rolling Code | |
| UGZ 433 | 433.92 | Fixed Code | |

Reichel

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

Rekers

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

Resch

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

RESPONSE

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|------------|--|
| - | 417.95 | Fixed Code | Only compatible with vehicles built prior to 2016. |

RIB

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|------------|--------------------------|
| MOON 27 | 26.995 | Fixed Code | Not compatible with HL5. |
| MOON 91 | 30.865 | Fixed Code | Not compatible with HL5. |
| MOON 433 | 433.92 | Fixed Code | |

Riedl

Compatible Device Manufacturers

If your device is not listed here, it may not be compatible with HomeLink. Don't see your device? [Get a universal receiver here.](#)

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| RFKCO-40-5 | 40.685 | Fixed Code | Not compatible with HL5. |
| T102497-40-5 | 40.685 | Fixed Code | Not compatible with HL5. |
| T397-40-2 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX02-40-2 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX03-40-1/5 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX04-40-15 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

Rode

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

roma / Silento

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|------------|--|
| Digital-211 | 433.92 | Fixed Code | |
| Digital-212 | 433.92 | Fixed Code | |
| Digital-214 | 433.92 | Fixed Code | |
| Digital-221 | 433.92 | Fixed Code | |
| Digital-222 | 433.92 | Fixed Code | |
| Digital-224 | 433.92 | Fixed Code | |
| Digital-231 | 433.92 | Fixed Code | |
| MT87A1 | 868.5 | Fixed Code | compatible since HomeLink Software Version 7 |
| MT87A2 | 868.5 | Fixed Code | compatible since HomeLink Software Version 7 |

RUKU

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|------------|--|
| SF40... | 40.662 | Fixed Code | Not compatible with HL5. |
| SA40... | 40.685 | Fixed Code | Not compatible with HL5. |
| SA434... | 433.92 | Fixed Code | |
| SF433... | 434.575 | Fixed Code | compatible since HomeLink Software Version 7 |
| SR 868-2 | 868.3 | Fixed Code | compatible since HomeLink SW version 7 |
| SR 868-4 | 868.3 | Fixed Code | compatible since HomeLink SW version 7 |

Compatible Device Manufacturers

If your device is not listed here, it may not be compatible with HomeLink. Don't see your device? [Get a universal receiver here.](#)

| | | | |
|---------|--------|--------------|--|
| SA868-1 | 868.35 | Rolling Code | compatible since HomeLink Software Version 7 |
|---------|--------|--------------|--|

Rundum Meir

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|------------|--|
| 7121 | 27.015 | Fixed Code | Not compatible with HL5. |
| 7221 | 40.685 | Fixed Code | Not compatible with HL5. |
| 7520 | 433.92 | Fixed Code | |
| 87135 | 868.3 | Fixed Code | compatible since HomeLink SW version 7 |

Ryterna

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

Rötör Service

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

Scarpatoni

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

Schalk

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|------------|-------|
| FSH-4 | 433.92 | Fixed Code | |
| FSH-8 | 433.92 | Fixed Code | |

Scharpf

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

Schellenberg

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|------------|-------|
| Mizar / 21250 | 433.92 | Fixed Code | |

Schmoelling

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| T102497-40-5 | 40.685 | Fixed Code | Not compatible with HL5. |
| T397-40-2 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

Schneider

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| RFKCO-40-5 | 40.685 | Fixed Code | Not compatible with HL5. |
| T102497-40-5 | 40.685 | Fixed Code | Not compatible with HL5. |
| T397-40-2 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX02-40-2 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX03-40-1/5 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX04-40-15 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

Schuetz

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| RFKCO-40-5 | 40.685 | Fixed Code | Not compatible with HL5. |
| T102497-40-5 | 40.685 | Fixed Code | Not compatible with HL5. |
| T397-40-2 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX02-40-2 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX04-40-15 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

Schwaben

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|------------|--------------------------|
| - | 40.685 | Fixed Code | Not compatible with HL5. |

Schweiger

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

SCOPE

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|------------|--|
| - | 418.01 | Fixed Code | Only compatible with vehicles built prior to 2016. |

seav

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------------|-----------------|--------------|--|
| - | 30.87 | Fixed Code | Not compatible with HL5. |
| BeEasy TX | 433.92 | Fixed Code | |
| BeEasy TX Rolling Code | 433.92 | Rolling Code | compatible since HomeLink Software Version 7 |
| BeHappy RH1 | 433.92 | Rolling Code | compatible since HomeLink Software Version 7 |
| BeHappy RH2 | 433.92 | Rolling Code | compatible since HomeLink Software Version 7 |
| BeHappy RH3 | 433.92 | Rolling Code | compatible since HomeLink Software Version 7 |
| BeHappy RS1 | 433.92 | Rolling Code | compatible since HomeLink Software Version 7 |

Compatible Device Manufacturers

If your device is not listed here, it may not be compatible with HomeLink. Don't see your device? [Get a universal receiver here.](#)

| | | | |
|-------------|--------|--------------|--|
| BeHappy RS2 | 433.92 | Rolling Code | compatible since HomeLink Software Version 7 |
| BeHappy RS3 | 433.92 | Rolling Code | compatible since HomeLink Software Version 7 |
| BeHappy S1 | 433.92 | Fixed Code | |
| BeHappy S2 | 433.92 | Fixed Code | |
| BeHappy S3 | 433.92 | Fixed Code | |
| TRS 1 | 433.92 | Rolling Code | compatible since HomeLink Software Version 7 |
| TRS 2 | 433.92 | Rolling Code | compatible since HomeLink Software Version 7 |
| TXS 1 | 433.92 | Fixed Code | |
| TXS 2 | 433.92 | Fixed Code | |
| TXS 3 | 433.92 | Fixed Code | |
| TXS 4 | 433.92 | Fixed Code | |
| TXS ESA | 433.92 | Fixed Code | |
| TXS ESA | 433.92 | Fixed Code | |
| TXS1 | 433.92 | Fixed Code | |
| TXS2 | 433.92 | Fixed Code | |
| TXS3 | 433.92 | Fixed Code | |

Sectic-Tec

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

Seculux

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|------------|--------------------------|
| RFKCO-40-5 | 40.685 | Fixed Code | Not compatible with HL5. |
| T102497-40-5 | 40.685 | Fixed Code | Not compatible with HL5. |
| T397-40-2 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX02-40-2 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX03-40-1/5 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX04-40-15 | 40.685 | Fixed Code | Not compatible with HL5. |

Seip

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|------------|--------------------------|
| - | 26.995 | Fixed Code | Not compatible with HL5. |
| - | 27.015 | Fixed Code | Not compatible with HL5. |
| 27 AM | 27.015 | Fixed Code | Not compatible with HL5. |

| | | | |
|-----------|--------|--------------|--------------------------|
| - | 40.685 | Fixed Code | Not compatible with HL5. |
| - | 40.685 | Fixed Code | Not compatible with HL5. |
| 40 AM | 40.685 | Fixed Code | Not compatible with HL5. |
| 40 FM | 40.685 | Fixed Code | Not compatible with HL5. |
| - | 433.92 | Fixed Code | |
| 433-12 AM | 433.92 | Fixed Code | |
| SKR 433 | 433.92 | Rolling Code | |
| SKRJ433 | 433.92 | Rolling Code | |

Selve

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|------------|--------------------------|
| 297112 | 40.685 | Fixed Code | Not compatible with HL5. |
| 297113 | 40.685 | Fixed Code | Not compatible with HL5. |
| 297114 | 40.685 | Fixed Code | Not compatible with HL5. |
| 297121 Mini | 40.685 | Fixed Code | Not compatible with HL5. |
| 297141 | 433.92 | Fixed Code | |
| 297142 | 433.92 | Fixed Code | |
| 297143 | 433.92 | Fixed Code | |
| 297145 Mini | 433.92 | Fixed Code | |
| 297344 | 433.92 | Fixed Code | |

Serai

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|------------|-------|
| OG/52 | 433.92 | Fixed Code | |
| OG/54 | 433.92 | Fixed Code | |
| OG/64 | 433.92 | Fixed Code | |

Sich Tel

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

Siebau

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|-------|
| MAX43-2 | 433.92 | Rolling Code | |
| MAX43-4 | 433.92 | Rolling Code | |
| MC43-2 | 433.92 | Fixed Code | |
| MCHS43-2 | 433.92 | Rolling Code | |
| MHS43-2 | 433.92 | Rolling Code | |

| | | | |
|----------|--------|--------------|--|
| MHS43-4 | 433.92 | Rolling Code | |
| MIX43-2 | 433.92 | Rolling Code | |
| MS43-2 | 433.92 | Fixed Code | |
| MS43-4 | 433.92 | Fixed Code | |
| Multibit | 433.92 | Fixed Code | |

Silento

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|------------|-------|
| Digital 211 | 433.92 | Fixed Code | |
| Digital 212 | 433.92 | Fixed Code | |
| Digital 214 | 433.92 | Fixed Code | |
| Digital 221 | 433.92 | Fixed Code | |
| Digital 222 | 433.92 | Fixed Code | |
| Digital 224 | 433.92 | Fixed Code | |
| Digital 231 | 433.92 | Fixed Code | |

Sistema

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

smd

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| LW27HS98 | 27.01 | Fixed Code | Not compatible with HL5. |
| LW27/40BS4N | 27.015 | Fixed Code | Not compatible with HL5. |
| LW40 MS3/4 | 27.015 | Fixed Code | Not compatible with HL5. |
| - | 40.685 | Fixed Code | Not compatible with HL5. |
| 40HS98K/U | 40.685 | Fixed Code | Not compatible with HL5.Red buttons are not compatible |
| 40MIU/IK | 40.685 | Fixed Code | Not compatible with HL5.Red buttons are not compatible |
| 40MS3/4 | 40.685 | Fixed Code | Not compatible with HL5.Red buttons are not compatible |
| LW40BSS4 | 40.685 | Fixed Code | Not compatible with HL5. |
| LW40HS98K/U | 40.685 | Rolling Code | Not compatible with HL5.not compatible with HL5 |
| MS4099U/K | 40.685 | Fixed Code | Not compatible with HL5.Red buttons are not compatible |
| - | 433.92 | Fixed Code | |
| LW433HS98FU/FK | 433.92 | Fixed Code | |

| | | | |
|-----------|--------|------------|--|
| LW433MIAU | 433.92 | Fixed Code | |
| LW433MS2 | 433.92 | Fixed Code | |

SMD

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| LW27HS98 | 27.01 | Fixed Code | Not compatible with HL5. |
| LW27/40BS4N | 27.015 | Fixed Code | Not compatible with HL5. |
| LW40 MS3/4 | 27.015 | Fixed Code | Not compatible with HL5. |
| - | 40.685 | Fixed Code | Not compatible with HL5. |
| 40HS98K/U | 40.685 | Fixed Code | Not compatible with HL5.Red buttons are not compatible |
| 40MIU/IK | 40.685 | Fixed Code | Not compatible with HL5.Red buttons are not compatible |
| 40MS3/4 | 40.685 | Fixed Code | Not compatible with HL5.Red buttons are not compatible |
| LW40BSS4 | 40.685 | Fixed Code | Not compatible with HL5. |
| LW40HS98K/U | 40.685 | Rolling Code | Not compatible with HL5.not compatible with HL5 |
| MS4099U/K | 40.685 | Fixed Code | Not compatible with HL5.Red buttons are not compatible |
| - | 433.92 | Fixed Code | |
| LW433HS98FU/FK | 433.92 | Fixed Code | |
| LW433MIAU | 433.92 | Fixed Code | |
| LW433MS2 | 433.92 | Fixed Code | |

Sommer

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| S-435-B | 27.015 | Fixed Code | Not compatible with HL5. |
| T102497-27-5 | 27.045 | Fixed Code | Not compatible with HL5. |
| RFKCO-40-5 | 40.685 | Fixed Code | Not compatible with HL5. |
| S-435-40 | 40.685 | Fixed Code | Not compatible with HL5. |
| T102497-40-5 | 40.685 | Fixed Code | Not compatible with HL5. |
| T397-40-2 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX02-40-2 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX03-40-1/5 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX04-40-15 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX02-434-2 | 434.42 | Rolling Code | |
| TX03-434-4 | 434.42 | Rolling Code | |
| TX03-434-4XP | 434.42 | Rolling Code | |
| TX03-868-4 | 868.3 | Rolling Code | compatible since HomeLink Software Version 7 |

| | | | |
|---------------|-------|--------------|--|
| TX03-868-4-XP | 868.3 | Rolling Code | compatible since HomeLink Software Version 7 |
| TX03-8-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

Sonico

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|------------|--------------------------|
| T102497-40-5 | 40.685 | Fixed Code | Not compatible with HL5. |
| T397-40-2 | 40.685 | Fixed Code | Not compatible with HL5. |

Sonnleitner

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

SPPF

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

STA

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

Stadelbauer

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

Standoor

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|------------|-------|
| G 4330 E | 433.92 | Fixed Code | |
| G 4332 E | 433.92 | Fixed Code | |
| G 4333 E | 433.92 | Fixed Code | |
| G 4335 E | 433.92 | Fixed Code | |

Stanley

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|------------|--------------------------|
| 1083-12 | 40.685 | Fixed Code | Not compatible with HL5. |

Steelline

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|------------|--|
| 868-4C | 868.3 | Fixed Code | compatible since HomeLink Software Version 7 |

Steinau

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|------------|--|
| DH 01 | 26.975 | Fixed Code | Not compatible with HL5. Valid for transmitters with green buttons |
| DH 02 | 26.975 | Fixed Code | Not compatible with HL5. Valid for transmitters with green buttons |
| DH 03 | 26.975 | Fixed Code | Not compatible with HL5. Valid for transmitters with green buttons |
| DH 04 | 26.975 | Fixed Code | Not compatible with HL5. Valid for transmitters with green buttons |
| FCT10b-40 | 40.685 | Fixed Code | Not compatible with HL5. |
| HS16-40 | 40.685 | Fixed Code | Not compatible with HL5. |
| HS2-40 | 40.685 | Fixed Code | Not compatible with HL5. Valid for transmitters with grey buttons |
| HS4-40 | 40.685 | Fixed Code | Not compatible with HL5. Valid for transmitters with grey buttons |
| HSE2-40 | 40.685 | Fixed Code | Not compatible with HL5. Valid for transmitters with grey buttons |
| HSM2-40 | 40.685 | Fixed Code | Not compatible with HL5. Valid for transmitters with grey buttons |
| HSM4-40 | 40.685 | Fixed Code | Not compatible with HL5. Valid for transmitters with grey buttons |

Compatible Device Manufacturers

If your device is not listed here, it may not be compatible with HomeLink. Don't see your device? [Get a universal receiver here.](#)

| | | | |
|------------|--------|--------------|--|
| S850 | 40.685 | Fixed Code | Not compatible with HL5. Valid for transmitters with grey buttons |
| RCT3b-433 | 433.92 | Rolling Code | |
| RS2-433 | 433.92 | Rolling Code | Valid for transmitters with yellow buttons |
| RS4-433 | 433.92 | Rolling Code | Valid for transmitters with yellow buttons |
| RSM2-433 | 433.92 | Rolling Code | Valid for transmitters with yellow buttons |
| RSM4-433 | 433.92 | Rolling Code | Valid for transmitters with yellow buttons |
| FCT10b-868 | 868.3 | Fixed Code | compatible since HomeLink Software Version 7 |
| FCT3b-868 | 868.3 | Fixed Code | compatible since HomeLink Software Version 7 |
| FFL12-868 | 868.3 | Fixed Code | compatible since HomeLink Software Version 7 |
| FIT2-868 | 868.3 | Fixed Code | compatible since HomeLink Software Version 7 |
| HS1-868 | 868.3 | Fixed Code | Valid for transmitters with blue buttons compatible since HomeLink Software Version 7 |
| HS16-868 | 868.3 | Fixed Code | compatible since HomeLink Software Version 7 |
| HS2-868 | 868.3 | Fixed Code | Valid for transmitters with blue buttons compatible since HomeLink Software Version 7 |
| HS4-868 | 868.3 | Fixed Code | Valid for transmitters with blue buttons compatible since HomeLink Software Version 7 |
| HSD2-868 | 868.3 | Fixed Code | compatible since HomeLink Software Version 7 |
| HSE2-868 | 868.3 | Fixed Code | Valid for transmitters with blue buttons compatible since HomeLink Software Version 7 |
| HSI-868 | 868.3 | Fixed Code | compatible since HomeLink Software Version 7 |

Compatible Device Manufacturers

If your device is not listed here, it may not be compatible with HomeLink. Don't see your device? [Get a universal receiver here.](#)

| | | | |
|------------|-------|------------|--|
| HSM2-868 | 868.3 | Fixed Code | Valid for transmitters with blue buttons compatible since HomeLink Software Version 7 |
| HSM4-868 | 868.3 | Fixed Code | Valid for transmitters with blue buttons compatible since HomeLink Software Version 7 |
| HSP4-868 | 868.3 | Fixed Code | Valid for transmitters with blue buttons compatible since HomeLink Software Version 7 |
| HSP4-C-868 | 868.3 | Fixed Code | compatible since HomeLink Software Version 7 |
| HSZ1-868 | 868.3 | Fixed Code | compatible since HomeLink Software Version 7 |
| HSZ2-868 | 868.3 | Fixed Code | compatible since HomeLink Software Version 7 |

Stock

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| T102497-40-5 | 40.685 | Fixed Code | Not compatible with HL5. |
| T397-40-2 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

SUPEERO

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|------------|--------------------------|
| SM1 | 26.995 | Fixed Code | Not compatible with HL5. |
| SM1DL | 26.995 | Fixed Code | Not compatible with HL5. |
| SM1MD | 26.995 | Fixed Code | Not compatible with HL5. |
| SM2 | 26.995 | Fixed Code | Not compatible with HL5. |
| SM2DL | 26.995 | Fixed Code | Not compatible with HL5. |
| SM2MD | 26.995 | Fixed Code | Not compatible with HL5. |
| SM3 | 26.995 | Fixed Code | Not compatible with HL5. |
| SM3DL | 26.995 | Fixed Code | Not compatible with HL5. |
| SM3MD | 26.995 | Fixed Code | Not compatible with HL5. |
| SM4 | 26.995 | Fixed Code | Not compatible with HL5. |
| SM4DL | 26.995 | Fixed Code | Not compatible with HL5. |
| SM4MD | 26.995 | Fixed Code | Not compatible with HL5. |
| SKLC1 | 40.685 | Fixed Code | Not compatible with HL5. |
| SKLC2 | 40.685 | Fixed Code | Not compatible with HL5. |

Compatible Device Manufacturers

If your device is not listed here, it may not be compatible with HomeLink. Don't see your device? [Get a universal receiver here.](#)

| | | | |
|---------|---------|------------|--------------------------|
| SKLC3 | 40.685 | Fixed Code | Not compatible with HL5. |
| SKLC4 | 40.685 | Fixed Code | Not compatible with HL5. |
| SKX1 | 433.995 | Fixed Code | |
| SKX1DL | 433.995 | Fixed Code | |
| SKX1MD | 433.995 | Fixed Code | |
| SKX2 | 433.995 | Fixed Code | |
| SKX22 | 433.995 | Fixed Code | |
| SKX2DL | 433.995 | Fixed Code | |
| SKX2MD | 433.995 | Fixed Code | |
| SKX3 | 433.995 | Fixed Code | |
| SKX33 | 433.995 | Fixed Code | |
| SKX33DL | 433.995 | Fixed Code | |
| SKX3DL | 433.995 | Fixed Code | |
| SKX3MD | 433.995 | Fixed Code | |
| SKX4 | 433.995 | Fixed Code | |
| SKX44 | 433.995 | Fixed Code | |
| SKX44DL | 433.995 | Fixed Code | |
| SKX4DL | 433.995 | Fixed Code | |
| SKX4MD | 433.995 | Fixed Code | |
| SKX88 | 433.995 | Fixed Code | |
| SKX88DL | 433.995 | Fixed Code | |
| SSKX4DL | 433.995 | Fixed Code | |
| SSKX4MD | 433.995 | Fixed Code | |

T+T

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|------------|--------------------------|
| T102497-40-5 | 40.685 | Fixed Code | Not compatible with HL5. |
| T397-40-2 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX02-40-2 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX03-40-1/5 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX04-40-15 | 40.685 | Fixed Code | Not compatible with HL5. |

Teckentrup

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|---------------------|-----------------|------------|-------|
| Digital 212 | 433.92 | Fixed Code | |
| Digital 214 | 433.92 | Fixed Code | |
| FSH06 | 433.92 | Fixed Code | |
| FSH07 | 433.92 | Fixed Code | |
| Digital 302 / 69212 | 868.6 | Fixed Code | |
| Digital 304 / 69213 | 868.6 | Fixed Code | |
| Digital 313 / 69226 | 868.6 | Fixed Code | |

Tedsen

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|------------|--------------------------|
| SM1.. | 26.995 | Fixed Code | Not compatible with HL5. |
| SM2 .. | 26.995 | Fixed Code | Not compatible with HL5. |
| SM3 .. | 26.995 | Fixed Code | Not compatible with HL5. |
| SM4 .. | 26.995 | Fixed Code | Not compatible with HL5. |
| SKX 2 .. | 433.92 | Fixed Code | |
| SKX1 .. | 433.92 | Fixed Code | |
| SKX3 .. | 433.92 | Fixed Code | |
| SKX4 .. | 433.92 | Fixed Code | |
| SKX2 .. | 433.975 | Fixed Code | |
| SKX3 .. | 433.975 | Fixed Code | |
| SKX4 .. | 433.975 | Fixed Code | |
| SKJ | 433.995 | Fixed Code | |
| SKX1 | 433.995 | Fixed Code | |
| SKX11MD | 433.995 | Fixed Code | |
| SKX1DL | 433.995 | Fixed Code | |
| SKX1HD | 433.995 | Fixed Code | |
| SKX1LC | 433.995 | Fixed Code | |
| SKX1MD | 433.995 | Fixed Code | |
| SKX1SL | 433.995 | Fixed Code | |
| SKX2 | 433.995 | Fixed Code | |

Compatible Device Manufacturers

If your device is not listed here, it may not be compatible with HomeLink. Don't see your device? [Get a universal receiver here.](#)

| | | | |
|---------|---------|------------|--|
| SKX22 | 433.995 | Fixed Code | |
| SKX22MD | 433.995 | Fixed Code | |
| SKX2DL | 433.995 | Fixed Code | |
| SKX2HD | 433.995 | Fixed Code | |
| SKX2LC | 433.995 | Fixed Code | |
| SKX2MD | 433.995 | Fixed Code | |
| SKX2SL | 433.995 | Fixed Code | |
| SKX3 | 433.995 | Fixed Code | |
| SKX33MD | 433.995 | Fixed Code | |
| SKX3DL | 433.995 | Fixed Code | |
| SKX3LC | 433.995 | Fixed Code | |
| SKX3MD | 433.995 | Fixed Code | |
| SKX3SL | 433.995 | Fixed Code | |
| SKX4 | 433.995 | Fixed Code | |
| SKX42A, | 433.995 | Fixed Code | |
| SKX42B | 433.995 | Fixed Code | |
| SKX44MD | 433.995 | Fixed Code | |
| SKX4DL | 433.995 | Fixed Code | |
| SKX4HD | 433.995 | Fixed Code | |
| SKX4LC | 433.995 | Fixed Code | |
| SKX4MD | 433.995 | Fixed Code | |
| SKX4SL | 433.995 | Fixed Code | |
| SKX62 | 433.995 | Fixed Code | |
| SKX6HD | 433.995 | Fixed Code | |
| SKX82 | 433.995 | Fixed Code | |
| SKX88MD | 433.995 | Fixed Code | |
| SKX6HD | 868.3 | Fixed Code | compatible since HomeLink Software Version 7 |

Teleco

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|------------|--------------------------|
| 131500-10 | 40.685 | Fixed Code | Not compatible with HL5. |
| 131500-20 | 40.685 | Fixed Code | Not compatible with HL5. |
| 131500-30 | 40.685 | Fixed Code | Not compatible with HL5. |

Thress

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

Turner

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

Timmermann

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

Tobias

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| RFKCO-40-5 | 40.685 | Fixed Code | Not compatible with HL5. |
| T102497-40-5 | 40.685 | Fixed Code | Not compatible with HL5. |
| T397-40-2 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX02-40-2 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX03-40-1/5 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX04-40-15 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

TOR AG

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|----------------------------|-----------------|------------|--------------------------|
| S206 (1 Kanal / 1 channel) | 27.015 | Fixed Code | Not compatible with HL5. |
| S206 (2 Kanal / 2 channel) | 27.015 | Fixed Code | Not compatible with HL5. |
| S206 (4 Kanal / 4 channel) | 27.015 | Fixed Code | Not compatible with HL5. |
| S215 (1 Kanal / 1 channel) | 27.015 | Fixed Code | Not compatible with HL5. |
| S215 (2 Kanal / 2 channel) | 27.015 | Fixed Code | Not compatible with HL5. |
| S235 | 27.015 | Fixed Code | Not compatible with HL5. |
| S406 (1 Kanal / 1 channel) | 40.685 | Fixed Code | Not compatible with HL5. |
| S406 (2 Kanal / 2 channel) | 40.685 | Fixed Code | Not compatible with HL5. |
| S406 (4 Kanal / 4 channel) | 40.685 | Fixed Code | Not compatible with HL5. |

| | | | |
|----------------------------|--------|------------|--------------------------|
| S415 (1 Kanal / 1 channel) | 40.685 | Fixed Code | Not compatible with HL5. |
| S415 (2 Kanal / 2 channel) | 40.685 | Fixed Code | Not compatible with HL5. |
| S435 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX 41 | 40.685 | Fixed Code | Not compatible with HL5. |
| 93121500 | 433.9 | Fixed Code | |
| TX 43 | 433.92 | Fixed Code | |

Torbau Kraemer

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

Torbau Pleidelsheim

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| T102497-40-5 | 40.685 | Fixed Code | Not compatible with HL5. |
| T397-40-2 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

Torbau Schwaben

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|------------|--------------------------|
| SM1 | 26.995 | Fixed Code | Not compatible with HL5. |
| SM2 | 26.995 | Fixed Code | Not compatible with HL5. |
| SM3 | 26.995 | Fixed Code | Not compatible with HL5. |
| SM4 | 26.995 | Fixed Code | Not compatible with HL5. |
| BE40L | 40.685 | Fixed Code | Not compatible with HL5. |
| HS2 | 40.685 | Fixed Code | Not compatible with HL5. |
| HS4 | 40.685 | Fixed Code | Not compatible with HL5. |
| SMX1 | 433.92 | Fixed Code | |
| SMX2 | 433.92 | Fixed Code | |
| SMX3 | 433.92 | Fixed Code | |
| SMX4 | 433.92 | Fixed Code | |

TorKomfort / ToKo

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|------------|--------------------------|
| 27AM | 26.995 | Fixed Code | Not compatible with HL5. |
| 40AM | 40.685 | Fixed Code | Not compatible with HL5. |

| | | | |
|---------|--------|--------------|--------------------------|
| 40FM | 40.685 | Fixed Code | Not compatible with HL5. |
| SKR433 | 433.92 | Rolling Code | |
| SKRJ433 | 433.92 | Rolling Code | |

Tormatic

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|--------------------------------|-----------------|--------------|-------|
| MAX 43-2 | 433.92 | Rolling Code | |
| MAX 43-4 | 433.92 | Rolling Code | |
| MC43-2 | 433.92 | Fixed Code | |
| MCHS 43-2 | 433.92 | Rolling Code | |
| MHS 43-2 | 433.92 | Rolling Code | |
| MHS 43-4 | 433.92 | Rolling Code | |
| MIX43-2 | 433.92 | Rolling Code | |
| MS43-2 | 433.92 | Fixed Code | |
| MSC43-4 | 433.92 | Fixed Code | |
| Multibit (1 Kanal / 1 channel) | 433.92 | Fixed Code | |
| Multibit (4 Kanal / 4 channel) | 433.92 | Fixed Code | |
| TX 43 | 433.92 | Fixed Code | |

Tormax

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

Torprimus

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|-------|
| TX03-868-4 | 868 | Rolling Code | |

Tousek

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|------------|--------------------------|
| (BT40) 131500-10 | 40.685 | Fixed Code | Not compatible with HL5. |
| (BT40) 131500-20 | 40.685 | Fixed Code | Not compatible with HL5. |
| (BT40) 131500-30 | 40.685 | Fixed Code | Not compatible with HL5. |

Traders

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------|-------|
|------------------|-----------------|--------|-------|

| | | | |
|--------------|--------|------------|--------------------------|
| - | 27.015 | Fixed Code | Not compatible with HL5. |
| 1K FM HS FHS | 40.685 | Fixed Code | Not compatible with HL5. |
| G4330E | 433.92 | Fixed Code | |
| G4332E | 433.92 | Fixed Code | |
| G4333E | 433.92 | Fixed Code | |
| G4335E | 433.92 | Fixed Code | |

Trido

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

Triebenbacher

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

Tubauto

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|------------|--------------------------|
| DH 01 | 26.975 | Fixed Code | Not compatible with HL5. |
| DH 02 | 26.975 | Fixed Code | Not compatible with HL5. |
| DH 03 | 26.975 | Fixed Code | Not compatible with HL5. |
| DH 04 | 26.975 | Fixed Code | Not compatible with HL5. |
| EcoStar 2 | 40.685 | Fixed Code | Not compatible with HL5. |
| EcoStar 4 | 40.685 | Fixed Code | Not compatible with HL5. |
| FCT10 | 40.685 | Fixed Code | Not compatible with HL5. |
| HS16 | 40.685 | Fixed Code | Not compatible with HL5. |
| HS2 | 40.685 | Fixed Code | Not compatible with HL5. |
| HS4 | 40.685 | Fixed Code | Not compatible with HL5. |
| HSE2 | 40.685 | Fixed Code | Not compatible with HL5. |
| HSM2 | 40.685 | Fixed Code | Not compatible with HL5. |
| HSM4 | 40.685 | Fixed Code | Not compatible with HL5. |
| RS2 | 433.92 | Fixed Code | |
| RS4 | 433.92 | Fixed Code | |
| RSE2 | 433.92 | Fixed Code | |
| RSM2 | 433.92 | Fixed Code | |
| RSM4 | 433.92 | Fixed Code | |

Compatible Device Manufacturers

If your device is not listed here, it may not be compatible with HomeLink. Don't see your device? [Get a universal receiver here.](#)

UNINORM

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

Universal

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|------------|-------|
| - | 433.92 | Fixed Code | |

V2

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|------------|-------|
| MATCH-B | 433.92 | Fixed Code | |
| TSC2 | 433.92 | Fixed Code | |
| TSC4 | 433.92 | Fixed Code | |
| TSR2 | 433.92 | Fixed Code | |
| TSR4 | 433.92 | Fixed Code | |

Valnes

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

Vanhalme

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|------------|--------------------------|
| MAC B 401 | 40.685 | Fixed Code | Not compatible with HL5. |
| MAC B 402 | 40.685 | Fixed Code | Not compatible with HL5. |
| MAC B 404 | 40.685 | Fixed Code | Not compatible with HL5. |

Vendôme

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

Weller

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| MT40A2_1 | 40.685 | Fixed Code | Not compatible with HL5. |
| MT40A2_2 | 40.685 | Fixed Code | Not compatible with HL5. |
| MT40A2_4 | 40.685 | Fixed Code | Not compatible with HL5. |
| MT87A1 | 868.5 | Rolling Code | compatible since HomeLink Software Version 7 |
| MT87A2 | 868.5 | Rolling Code | compatible since HomeLink Software Version 7 |

WERMELINGER

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

WESSEX

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|------------|--|
| - | 417.98 | Fixed Code | Only compatible with vehicles built prior to 2016. |

Wi?niowski

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|-------------------------------------|
| 2A433 | 433.92 | Rolling Code | compatible since Software version 8 |
| 2k433 | 433.92 | Rolling Code | compatible since Software version 8 |
| 4A433 | 433.92 | Rolling Code | compatible since Software version 8 |
| 4GO | 433.92 | Rolling Code | compatible since Software version 8 |
| 4k433 | 433.92 | Rolling Code | compatible since Software version 8 |
| COVER | 433.92 | Rolling Code | compatible since Software version 8 |

Wickes

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------|-------|
|------------------|-----------------|--------|-------|

Compatible Device Manufacturers

If your device is not listed here, it may not be compatible with HomeLink. Don't see your device? [Get a universal receiver here.](#)

| | | | |
|----------|--------|------------|--|
| - | 417.96 | Fixed Code | Only compatible with vehicles built prior to 2016. |
| 200087 | 433.92 | Fixed Code | |
| G 4335 E | 433.92 | Fixed Code | |

Woelm

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|------------|--|
| 1110009141 | 27.015 | Fixed Code | Not compatible with HL5. |
| 1110009142 | 27.015 | Fixed Code | Not compatible with HL5. |
| 1110009143 | 868.3 | Fixed Code | compatible since HomeLink Software Version 7 |
| 1110009144 | 868.3 | Fixed Code | compatible since HomeLink Software Version 7 |

Wotan

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|------------|--------------------------|
| 11 | 27.145 | Fixed Code | Not compatible with HL5. |
| G750E | 27.145 | Fixed Code | Not compatible with HL5. |
| G752E | 27.145 | Fixed Code | Not compatible with HL5. |
| G754E | 27.145 | Fixed Code | Not compatible with HL5. |
| 11-1B | 433.92 | Fixed Code | |
| 11-2B | 433.92 | Fixed Code | |
| 11-3B | 433.92 | Fixed Code | |
| G4330E | 433.92 | Fixed Code | |
| G4333E | 433.92 | Fixed Code | |
| G4335E | 433.92 | Fixed Code | |

WURM

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |

Zweygart

| Transmitter Name | Frequency [MHz] | Coding | Notes |
|------------------|-----------------|--------------|--|
| RFKCO-40-5 | 40.685 | Fixed Code | Not compatible with HL5. |
| T102497-40-5 | 40.685 | Fixed Code | Not compatible with HL5. |
| T397-40-2 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX02-40-2 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX03-40-1/5 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX04-40-15 | 40.685 | Fixed Code | Not compatible with HL5. |
| TX03-868-4 | 868.8 | Rolling Code | compatible since HomeLink Software Version 7 |